
TPTL · Tripura Power Transmission Limited


AI TRANSMISSION TOWER INSPECTION & PROGRESS REPORT

High-Resolution Aerial Vision & Structural Defect Audit

Report ID: 36E7A6F502394EBD80CABA2A97A66871
Batch: BATCH-36E7A6F5
Period: 29 Sep 2025 – 29 Sep 2026 (1Y)

1. ANALYTICS & DEFECT SEVERITY DISTRIBUTION





Healthy 146 (94%) · 156 Towers · Critical 10 (6%)

Vegetation Foreign Object Rust Missing Bolt Insulator Defect

Showing 8 of 156 towers

Processing & Camera Details

Property	Value	Property	Value
Total Images	25	Foreign Object model	Enabled
Insulator Defect model	Enabled	Missing Bolt model	Enabled
Rust model	Enabled	Vegetation model	Enabled
Camera	DJI	Camera model	FC3582

Image-wise Findings

Image	Foreign Object Count	Insulator Defect Count	Missing Bolt Count	Rust Count	Vegetation Count	Severity	Go To Page
img7.jpg	0	0	0	1 (1.649%)	0	Critical	4
100124.jpg	0	1	0	0	0	Critical	4
2.jpg	0	0	0	0	1	Critical	4
3.png	0	0	0	0	4	Critical	6
3.jpg	0	0	0	0	1	Critical	6
a57681...939.png	6	0	0	0	0	Critical	8
9db618...429.png	1	0	0	0	2	Critical	8
img8.jpg	0	0	0	3 (2.390%)	0	Critical	10
DJI_0477.JPG	0	0	0	0	0	Healthy	10
c4a086...755.png	5	0	0	0	2	Critical	10
c4a086...755.png	5	0	0	0	2	Critical	11
DJI_0481.JPG	0	0	5	0	0	Critical	13
DJI_0479.JPG	0	0	0	0	0	Healthy	13

Confidential document for internal transmission asset maintenance only.

Image	Foreign Object Count	Insulator Defect Count	Missing Bolt Count	Rust Count	Vegetation Count	Severity	Go To Page
DJI_0532.JPG	0	0	2	0	1	Critical	15
DJI_0484.JPG	0	0	1	1 (0.278%)	0	Critical	15
Screen...828.png	0	0	0	0	1	Critical	17
DJI_0561.JPG	0	0	0	0	0	Healthy	17
DJI_0533.JPG	0	0	0	0	0	Healthy	17
Gemini...9i0.png	1	0	0	0	0	Critical	19
DJI_0582.JPG	0	0	0	0	1	Critical	19
img04578.png	0	0	0	4 (3.350%)	0	Critical	21
image_002.jpg	0	0	1	0	0	Critical	21
Screen...935.png	0	0	0	0	2	Critical	23
img4.png	0	0	0	1 (4.405%)	0	Critical	23
img2.png	0	0	0	1 (14.704%)	1	Critical	23

TRIPURA POWER TRANSMISSION LIMITED
TPTL

2. TOWER-WISE INSPECTION DETAILS (156 towers · 25 anomalies)

TOWER SUMMARY · 1 OF 156

No. 0009 Critical

BELONIA-SABROOM-T09

3 anomalies · Inspected 25 Sep 2026, 18:30 IST · Voltage 0 kV



Tower no	0009	Tower name	BELONIA-SABROOM-T09
Latitude	23.233887	Longitude	91.492255
X	N/A	Y	N/A
Z	203.00	Client / zone	TD_Udaipur
Inspection	25 Sep 2026, 18:30 IST	Report generated	29 Sep 2026, 11:31 IST
Transmission line	SABROOM C1	Line voltage	0 kV

ANOMALY SUMMARY · 3 detected

#	Anomaly	Section	Component	Criticality
1	Rust	N/A	Rust	Critical
2	Insulator	N/A	Missing / Broken	Critical
3	Veg	N/A	Vegetation	Critical

TRIPURA POWER TRANSMISSION LIMITED
TPTL




FINDING 1

Rust

AI analysis detected 1 rust/corrosion detection. 1 detection is classified as critical. Highest detection confidence: 65.6%. Prompt inspection and appropriate corrective action are recommended.

Tower	No. 0009
Section	N/A
Point / component	Rust
Insulator no.	N/A
Anomaly type	Rust
Criticality	Critical
Expected result	N/A



FINDING 2

Insulator

AI analysis detected 1 missing/broken insulator detection. Highest detection confidence: 98.9%. Prompt inspection and appropriate corrective action are recommended.

Tower	No. 0009
Section	N/A
Point / component	Missing / Broken
Insulator no.	N/A
Anomaly type	Insulator
Criticality	Critical
Expected result	N/A



FINDING 3

Veg

AI analysis detected 1 vegetation detection. 1 detection is classified as critical. Highest detection confidence: 55.6%. Prompt inspection and appropriate corrective action are recommended.

Tower	No. 0009
Section	N/A
Point / component	Vegetation
Insulator no.	N/A
Anomaly type	Veg
Criticality	Critical
Expected result	N/A

No. 0010 Critical

BELONIA-SABROOM-T10

2 anomalies · Inspected 25 Sep 2026, 18:30 IST · Voltage 0 kV




Tower no	0010	Tower name	BELONIA-SABROOM-T10
Latitude	23.232037	Longitude	91.494758
X	N/A	Y	N/A
Z	267.00	Client / zone	TD_Udaipur
Inspection	25 Sep 2026, 18:30 IST	Report generated	29 Sep 2026, 11:31 IST
Transmission line	SABROOM C1	Line voltage	0 kV

ANOMALY SUMMARY · 2 detected

#	Anomaly	Section	Component	Criticality
1	Veg	N/A	Vegetation	Critical
2	Veg	N/A	Vegetation	Critical

TRIPURA POWER TRANSMISSION LIMITED
TPTL



FINDING 1

Veg

AI analysis detected 4 vegetation detections. 4 detections are classified as critical. Highest detection confidence: 80.2%. Prompt inspection and appropriate corrective action are recommended.

Tower	No. 0010
Section	N/A
Point / component	Vegetation
Insulator no.	N/A
Anomaly type	Veg
Criticality	Critical
Expected result	N/A



FINDING 2

Veg

AI analysis detected 1 vegetation detection. 1 detection is classified as critical. Highest detection confidence: 70.9%. Prompt inspection and appropriate corrective action are recommended.

Tower	No. 0010
Section	N/A
Point / component	Vegetation
Insulator no.	N/A
Anomaly type	Veg
Criticality	Critical
Expected result	N/A

TRIPURA POWER TRANSMISSION LIMITED
TPTL

TOWER SUMMARY · 3 OF 156

No. 0011 Critical

BELONIA-SABROOM-T11

2 anomalies · Inspected 25 Sep 2026, 18:30 IST · Voltage 0 kV



Tower no	0011	Tower name	BELONIA-SABROOM-T11
Latitude	23.231335	Longitude	91.496205
X	N/A	Y	N/A
Z	275.00	Client / zone	TD_Udaipur
Inspection	25 Sep 2026, 18:30 IST	Report generated	29 Sep 2026, 11:31 IST
Transmission line	SABROOM C1	Line voltage	0 kV

ANOMALY SUMMARY · 2 detected

#	Anomaly	Section	Component	Criticality
1	Foreign Obj	N/A	Foreign Object	Critical
2	Veg	N/A	Foreign Object	Critical

TRIPURA POWER TRANSMISSION LIMITED
TPTL



FINDING 1

Foreign Obj

AI analysis detected 6 foreign object detections. 6 detections are classified as critical. Highest detection confidence: 87.3%. Prompt inspection and appropriate corrective action are recommended.

Tower	No. 0011
Section	N/A
Point / component	Foreign Object
Insulator no.	N/A
Anomaly type	Foreign Obj
Criticality	Critical
Expected result	N/A



FINDING 2

Veg

AI analysis detected 1 foreign object detection, 2 vegetation detections. 3 detections are classified as critical. Highest detection confidence: 83.2%. Prompt inspection and appropriate corrective action are recommended.

Tower	No. 0011
Section	N/A
Point / component	Foreign Object
Insulator no.	N/A
Anomaly type	Veg
Criticality	Critical
Expected result	N/A

TRIPURA POWER TRANSMISSION LIMITED
TPTL

No. 0012 Critical

BELONIA-SABROOM-T12

4 anomalies · Inspected 25 Sep 2026, 18:30 IST · Voltage 0 kV



Tower no	0012	Tower name	BELONIA-SABROOM-T12
Latitude	23.230863	Longitude	91.497144
X	N/A	Y	N/A
Z	217.00	Client / zone	TD_Udaipur
Inspection	25 Sep 2026, 18:30 IST	Report generated	29 Sep 2026, 11:31 IST
Transmission line	SABROOM C1	Line voltage	0 kV

ANOMALY SUMMARY · 4 detected

#	Anomaly	Section	Component	Criticality
1	Rust	N/A	Rust	Critical
2	DJI_0477.JPG	N/A	N/A	Healthy
3	Veg	N/A	Foreign Object	Critical
4	Veg	N/A	N/A	Critical

TRIPURA POWER TRANSMISSION LIMITED
TPTL



FINDING 1

Rust

AI analysis detected 3 rust/corrosion detections. 3 detections are classified as critical. Highest detection confidence: 70.6%. Prompt inspection and appropriate corrective action are recommended.

Tower	No. 0012
Section	N/A
Point / component	Rust
Insulator no.	N/A
Anomaly type	Rust
Criticality	Critical
Expected result	N/A



FINDING 2

DJI_0477.JPG

DJI_0477.JPG at tower no. 0012

Tower	No. 0012
Section	N/A
Point / component	N/A
Insulator no.	N/A
Anomaly type	DJI_0477.JPG
Criticality	Healthy
Expected result	N/A



FINDING 3

Veg

AI analysis detected 5 foreign object detections, 2 vegetation detections. 7 detections are classified as critical. Highest detection confidence: 86.8%. Prompt inspection and appropriate corrective action are recommended.

Tower	No. 0012
Section	N/A
Point / component	Foreign Object
Insulator no.	N/A
Anomaly type	Veg
Criticality	Critical
Expected result	N/A



FINDING 4

Veg

Veg at tower no. 0012

Tower	**No. 0012**
Section	**N/A**
Point / component	**N/A**
Insulator no.	**N/A**
Anomaly type	**Veg**
Criticality	**Critical**
Expected result	**N/A**

TRIPURA POWER TRANSMISSION LIMITED
TPTL

TOWER SUMMARY · 5 OF 156

No. 0013 Critical

BELONIA-SABROOM-T13

2 anomalies · Inspected 25 Sep 2026, 18:30 IST · Voltage 0 kV



Tower no	0013	Tower name	BELONIA-SABROOM-T13
Latitude	23.230376	Longitude	91.499278
X	N/A	Y	N/A
Z	174.00	Client / zone	TD_Udaipur
Inspection	25 Sep 2026, 18:30 IST	Report generated	29 Sep 2026, 11:31 IST
Transmission line	SABROOM C1	Line voltage	0 kV

ANOMALY SUMMARY · 2 detected

#	Anomaly	Section	Component	Criticality
1	Missing Bolt	N/A	Missing Bolt	Critical
2	DJI_0479.JPG	N/A	N/A	Healthy

TRIPURA POWER TRANSMISSION LIMITED
TPTL



FINDING 1

Missing Bolt

AI analysis detected 5 missing bolt detections. 5 detections are classified as critical. Highest detection confidence: 59.4%. Prompt inspection and appropriate corrective action are recommended.

Tower	No. 0013
Section	N/A
Point / component	Missing Bolt
Insulator no.	N/A
Anomaly type	Missing Bolt
Criticality	Critical
Expected result	N/A



FINDING 2

DJI_0479.JPG

DJI_0479.JPG at tower no. 0013

Tower	No. 0013
Section	N/A
Point / component	N/A
Insulator no.	N/A
Anomaly type	DJI_0479.JPG
Criticality	Healthy
Expected result	N/A

TRIPURA POWER TRANSMISSION LIMITED
TPTL

No. 0014 Critical

BELONIA-SABROOM-T14

2 anomalies · Inspected 25 Sep 2026, 18:30 IST · Voltage 0 kV



Tower no	0014	Tower name	BELONIA-SABROOM-T14
Latitude	23.229962	Longitude	91.501319
X	N/A	Y	N/A
Z	238.00	Client / zone	TD_Udaipur
Inspection	25 Sep 2026, 18:30 IST	Report generated	29 Sep 2026, 11:31 IST
Transmission line	SABROOM C1	Line voltage	0 kV

ANOMALY SUMMARY · 2 detected

#	Anomaly	Section	Component	Criticality
1	Missing Bolt	N/A	Vegetation	Critical
2	Rust	N/A	Rust	Critical

TRIPURA POWER TRANSMISSION LIMITED
TPTL



FINDING 1

Missing Bolt

AI analysis detected 1 vegetation detection, 2 missing bolt detections. 3 detections are classified as critical. Highest detection confidence: 76.4%. Prompt inspection and appropriate corrective action are recommended.

Tower	No. 0014
Section	N/A
Point / component	Vegetation
Insulator no.	N/A
Anomaly type	Missing Bolt
Criticality	Critical
Expected result	N/A



FINDING 2

Rust

AI analysis detected 1 rust/corrosion detection, 1 missing bolt detection. 2 detections are classified as critical. Highest detection confidence: 80.8%. Prompt inspection and appropriate corrective action are recommended.

Tower	No. 0014
Section	N/A
Point / component	Rust
Insulator no.	N/A
Anomaly type	Rust
Criticality	Critical
Expected result	N/A

TRIPURA POWER TRANSMISSION LIMITED
TPTL

No. 0015 Critical

BELONIA-SABROOM-T15

3 anomalies · Inspected 25 Sep 2026, 18:30 IST · Voltage 0 kV




Tower no	0015	Tower name	BELONIA-SABROOM-T15
Latitude	23.229508	Longitude	91.504175
X	N/A	Y	N/A
Z	155.00	Client / zone	TD_Udaipur
Inspection	25 Sep 2026, 18:30 IST	Report generated	29 Sep 2026, 11:31 IST
Transmission line	SABROOM C1	Line voltage	0 kV

ANOMALY SUMMARY · 3 detected

#	Anomaly	Section	Component	Criticality
1	Veg	N/A	Vegetation	Critical
2	DJI_0561.JPG	N/A	N/A	Healthy
3	DJI_0533.JPG	N/A	N/A	Healthy

TRIPURA POWER TRANSMISSION LIMITED
TPTL



FINDING 1

Veg

AI analysis detected 1 vegetation detection. 1 detection is classified as critical. Highest detection confidence: 79.2%. Prompt inspection and appropriate corrective action are recommended.

Tower	No. 0015
Section	N/A
Point / component	Vegetation
Insulator no.	N/A
Anomaly type	Veg
Criticality	Critical
Expected result	N/A



FINDING 2

DJI_0561.JPG

DJI_0561.JPG at tower no. 0015

Tower	No. 0015
Section	N/A
Point / component	N/A
Insulator no.	N/A
Anomaly type	DJI_0561.JPG
Criticality	Healthy
Expected result	N/A



FINDING 3

DJI_0533.JPG

DJI_0533.JPG at tower no. 0015

Tower	No. 0015
Section	N/A
Point / component	N/A
Insulator no.	N/A
Anomaly type	DJI_0533.JPG
Criticality	Healthy
Expected result	N/A

TOWER SUMMARY · 8 OF 156

No. 0016 Critical

BELONIA-SABROOM-T16

2 anomalies · Inspected 25 Sep 2026, 18:30 IST · Voltage 0 kV



Tower no	0016	Tower name	BELONIA-SABROOM-T16
Latitude	23.228211	Longitude	91.505261
X	N/A	Y	N/A
Z	164.00	Client / zone	TD_Udaipur
Inspection	25 Sep 2026, 18:30 IST	Report generated	29 Sep 2026, 11:31 IST
Transmission line	SABROOM C1	Line voltage	0 kV

ANOMALY SUMMARY · 2 detected

#	Anomaly	Section	Component	Criticality
1	Foreign Obj	N/A	Foreign Object	Critical
2	Veg	N/A	Vegetation	Critical

TRIPURA POWER TRANSMISSION LIMITED
TPTL



FINDING 1

Foreign Obj

AI analysis detected 1 foreign object detection. 1 detection is classified as critical. Highest detection confidence: 84.9%. Prompt inspection and appropriate corrective action are recommended.

Tower	No. 0016
Section	N/A
Point / component	Foreign Object
Insulator no.	N/A
Anomaly type	Foreign Obj
Criticality	Critical
Expected result	N/A



FINDING 2

Veg

AI analysis detected 1 vegetation detection. 1 detection is classified as critical. Highest detection confidence: 57.3%. Prompt inspection and appropriate corrective action are recommended.

Tower	No. 0016
Section	N/A
Point / component	Vegetation
Insulator no.	N/A
Anomaly type	Veg
Criticality	Critical
Expected result	N/A

TRIPURA POWER TRANSMISSION LIMITED
TPTL

TOWER SUMMARY · 9 OF 156

No. 0017 Critical

BELONIA-SABROOM-T17

2 anomalies · Inspected 25 Sep 2026, 18:30 IST · Voltage 0 kV



Tower no	0017	Tower name	BELONIA-SABROOM-T17
Latitude	23.226427	Longitude	91.506070
X	N/A	Y	N/A
Z	156.00	Client / zone	TD_Udaipur
Inspection	25 Sep 2026, 18:30 IST	Report generated	29 Sep 2026, 11:31 IST
Transmission line	SABROOM C1	Line voltage	0 kV

ANOMALY SUMMARY · 2 detected

#	Anomaly	Section	Component	Criticality
1	Rust	N/A	Rust	Critical
2	Missing Bolt	N/A	Missing Bolt	Critical

TRIPURA POWER TRANSMISSION LIMITED
TPTL



FINDING 1

Rust

AI analysis detected 4 rust/corrosion detections. 4 detections are classified as critical. Highest detection confidence: 85.0%. Prompt inspection and appropriate corrective action are recommended.

Tower	No. 0017
Section	N/A
Point / component	Rust
Insulator no.	N/A
Anomaly type	Rust
Criticality	Critical
Expected result	N/A



FINDING 2

Missing Bolt

AI analysis detected 1 missing bolt detection. 1 detection is classified as critical. Highest detection confidence: 67.0%. Prompt inspection and appropriate corrective action are recommended.

Tower	No. 0017
Section	N/A
Point / component	Missing Bolt
Insulator no.	N/A
Anomaly type	Missing Bolt
Criticality	Critical
Expected result	N/A

TRIPURA POWER TRANSMISSION LIMITED
TPTL

No. 0018 Critical

BELONIA-SABROOM-T18

3 anomalies · Inspected 25 Sep 2026, 18:30 IST · Voltage 0 kV




Tower no	0018	Tower name	BELONIA-SABROOM-T18
Latitude	23.225672	Longitude	91.508571
X	N/A	Y	N/A
Z	172.00	Client / zone	TD_Udaipur
Inspection	25 Sep 2026, 18:30 IST	Report generated	29 Sep 2026, 11:31 IST
Transmission line	SABROOM C1	Line voltage	0 kV

ANOMALY SUMMARY · 3 detected

#	Anomaly	Section	Component	Criticality
1	Veg	N/A	Vegetation	Critical
2	Rust	N/A	Rust	Critical
3	Rust	N/A	Rust	Critical

TRIPURA POWER TRANSMISSION LIMITED
TPTL



FINDING 1

Veg

AI analysis detected 2 vegetation detections. 2 detections are classified as critical. Highest detection confidence: 84.2%. Prompt inspection and appropriate corrective action are recommended.

Tower	No. 0018
Section	N/A
Point / component	Vegetation
Insulator no.	N/A
Anomaly type	Veg
Criticality	Critical
Expected result	N/A



FINDING 2

Rust

AI analysis detected 1 rust/corrosion detection. 1 detection is classified as critical. Highest detection confidence: 54.6%. Prompt inspection and appropriate corrective action are recommended.

Tower	No. 0018
Section	N/A
Point / component	Rust
Insulator no.	N/A
Anomaly type	Rust
Criticality	Critical
Expected result	N/A



FINDING 3

Rust

AI analysis detected 1 rust/corrosion detection, 1 vegetation detection. 2 detections are classified as critical. Highest detection confidence: 76.9%. Prompt inspection and appropriate corrective action are recommended.

Tower	No. 0018
Section	N/A
Point / component	Rust
Insulator no.	N/A
Anomaly type	Rust
Criticality	Critical
Expected result	N/A

TOWER SUMMARY · 11 OF 156

No. 0001 Healthy

BELONIA-SABROOM-T01

0 anomalies · Inspected N/A · Voltage 0 kV



Tower no	0001	Tower name	BELONIA-SABROOM-T01
Latitude	23.246305	Longitude	91.478044
X	N/A	Y	N/A
Z	174.00	Client / zone	TD_Udaipur
Inspection	N/A	Report generated	29 Sep 2026, 11:31 IST
Transmission line	SABROOM C1	Line voltage	0 kV

ANOMALY SUMMARY · 0 detected

No anomalies detected for this tower.

TRIPURA POWER TRANSMISSION LIMITED
TPTL

No anomalies detected for this tower.

TRIPURA POWER TRANSMISSION LIMITED
TPTL

No. 0002 Healthy

BELONIA-SABROOM-T02

0 anomalies · Inspected N/A · Voltage 0 kV



Tower no	0002	Tower name	BELONIA-SABROOM-T02
Latitude	23.244595	Longitude	91.479868
X	N/A	Y	N/A
Z	164.00	Client / zone	TD_Udaipur
Inspection	N/A	Report generated	29 Sep 2026, 11:31 IST
Transmission line	SABROOM C1	Line voltage	0 kV

ANOMALY SUMMARY · 0 detected

No anomalies detected for this tower.

TRIPURA POWER TRANSMISSION LIMITED
TPTL

No anomalies detected for this tower.

No. 0003 Healthy

BELONIA-SABROOM-T03

0 anomalies · Inspected N/A · Voltage 0 kV



Tower no	0003	Tower name	BELONIA-SABROOM-T03
Latitude	23.242590	Longitude	91.482135
X	N/A	Y	N/A
Z	184.00	Client / zone	TD_Udaipur
Inspection	N/A	Report generated	29 Sep 2026, 11:31 IST
Transmission line	SABROOM C1	Line voltage	0 kV

ANOMALY SUMMARY · 0 detected

No anomalies detected for this tower.

TRIPURA POWER TRANSMISSION LIMITED
TPTL

No anomalies detected for this tower.

TOWER SUMMARY · 14 OF 156

No. 0004 Healthy

BELONIA-SABROOM-T04

0 anomalies · Inspected N/A · Voltage 0 kV



Tower no	0004	Tower name	BELONIA-SABROOM-T04
Latitude	23.240985	Longitude	91.483799
X	N/A	Y	N/A
Z	190.00	Client / zone	TD_Udaipur
Inspection	N/A	Report generated	29 Sep 2026, 11:31 IST
Transmission line	SABROOM C1	Line voltage	0 kV

ANOMALY SUMMARY · 0 detected

No anomalies detected for this tower.

TRIPURA POWER TRANSMISSION LIMITED
TPTL

No anomalies detected for this tower.

TOWER SUMMARY · 15 OF 156

No. 0005 Healthy

BELONIA-SABROOM-T05

0 anomalies · Inspected N/A · Voltage 0 kV



Tower no	0005	Tower name	BELONIA-SABROOM-T05
Latitude	23.239975	Longitude	91.485662
X	N/A	Y	N/A
Z	185.00	Client / zone	TD_Udaipur
Inspection	N/A	Report generated	29 Sep 2026, 11:31 IST
Transmission line	SABROOM C1	Line voltage	0 kV

ANOMALY SUMMARY · 0 detected

No anomalies detected for this tower.

TRIPURA POWER TRANSMISSION LIMITED
TPTL

No anomalies detected for this tower.

TOWER SUMMARY · 16 OF 156

No. 0006 Healthy

BELONIA-SABROOM-T06

0 anomalies · Inspected N/A · Voltage 0 kV



Tower no	0006	Tower name	BELONIA-SABROOM-T06
Latitude	23.238442	Longitude	91.486817
X	N/A	Y	N/A
Z	197.00	Client / zone	TD_Udaipur
Inspection	N/A	Report generated	29 Sep 2026, 11:31 IST
Transmission line	SABROOM C1	Line voltage	0 kV

ANOMALY SUMMARY · 0 detected

No anomalies detected for this tower.

TRIPURA POWER TRANSMISSION LIMITED
TPTL

No anomalies detected for this tower.

TOWER SUMMARY · 17 OF 156

No. 0007 Healthy

BELONIA-SABROOM-T07

0 anomalies · Inspected N/A · Voltage 0 kV



Tower no	0007	Tower name	BELONIA-SABROOM-T07
Latitude	23.236419	Longitude	91.488314
X	N/A	Y	N/A
Z	199.00	Client / zone	TD_Udaipur
Inspection	N/A	Report generated	29 Sep 2026, 11:31 IST
Transmission line	SABROOM C1	Line voltage	0 kV

ANOMALY SUMMARY · 0 detected

No anomalies detected for this tower.

TRIPURA POWER TRANSMISSION LIMITED
TPTL

No anomalies detected for this tower.

TOWER SUMMARY · 18 OF 156

No. 0008 Healthy

BELONIA-SABROOM-T08

0 anomalies · Inspected N/A · Voltage 0 kV



Tower no	0008	Tower name	BELONIA-SABROOM-T08
Latitude	23.235079	Longitude	91.490496
X	N/A	Y	N/A
Z	177.00	Client / zone	TD_Udaipur
Inspection	N/A	Report generated	29 Sep 2026, 11:31 IST
Transmission line	SABROOM C1	Line voltage	0 kV

ANOMALY SUMMARY · 0 detected

No anomalies detected for this tower.

TRIPURA POWER TRANSMISSION LIMITED
TPTL

No anomalies detected for this tower.

TOWER SUMMARY · 19 OF 156

No. 0019 Healthy

BELONIA-SABROOM-T19

0 anomalies · Inspected N/A · Voltage 0 kV



Tower no	0019	Tower name	BELONIA-SABROOM-T19
Latitude	23.223698	Longitude	91.510438
X	N/A	Y	N/A
Z	165.00	Client / zone	TD_Udaipur
Inspection	N/A	Report generated	29 Sep 2026, 11:31 IST
Transmission line	SABROOM C1	Line voltage	0 kV

ANOMALY SUMMARY · 0 detected

No anomalies detected for this tower.

TRIPURA POWER TRANSMISSION LIMITED
TPTL

No anomalies detected for this tower.

TOWER SUMMARY · 20 OF 156

No. 0020 Healthy

BELONIA-SABROOM-T20

0 anomalies · Inspected N/A · Voltage 0 kV



Tower no	0020	Tower name	BELONIA-SABROOM-T20
Latitude	23.222809	Longitude	91.513997
X	N/A	Y	N/A
Z	185.00	Client / zone	TD_Udaipur
Inspection	N/A	Report generated	29 Sep 2026, 11:31 IST
Transmission line	SABROOM C1	Line voltage	0 kV

ANOMALY SUMMARY · 0 detected

No anomalies detected for this tower.

TRIPURA POWER TRANSMISSION LIMITED
TPTL

No anomalies detected for this tower.

TRIPURA POWER TRANSMISSION LIMITED
TPTL

No. 0021 Healthy

BELONIA-SABROOM-T21

0 anomalies · Inspected N/A · Voltage 0 kV



Tower no	0021	Tower name	BELONIA-SABROOM-T21
Latitude	23.222407	Longitude	91.515801
X	N/A	Y	N/A
Z	193.00	Client / zone	TD_Udaipur
Inspection	N/A	Report generated	29 Sep 2026, 11:31 IST
Transmission line	SABROOM C1	Line voltage	0 kV

ANOMALY SUMMARY · 0 detected

No anomalies detected for this tower.

TRIPURA POWER TRANSMISSION LIMITED
TPTL

No anomalies detected for this tower.

No. 0022 Healthy

BELONIA-SABROOM-T22

0 anomalies · Inspected N/A · Voltage 0 kV



Tower no	0022	Tower name	BELONIA-SABROOM-T22
Latitude	23.222111	Longitude	91.518015
X	N/A	Y	N/A
Z	212.00	Client / zone	TD_Udaipur
Inspection	N/A	Report generated	29 Sep 2026, 11:31 IST
Transmission line	SABROOM C1	Line voltage	0 kV

ANOMALY SUMMARY · 0 detected

No anomalies detected for this tower.

TRIPURA POWER TRANSMISSION LIMITED
TPTL

No anomalies detected for this tower.

TRIPURA POWER TRANSMISSION LIMITED
TPTL

No. 0023 Healthy

BELONIA-SABROOM-T23

0 anomalies · Inspected N/A · Voltage 0 kV

Tower no	0023	Tower name	BELONIA-SABROOM-T23
Latitude	23.221564	Longitude	91.520431
X	N/A	Y	N/A
Z	226.00	Client / zone	TD_Udaipur
Inspection	N/A	Report generated	29 Sep 2026, 11:31 IST
Transmission line	SABROOM C1	Line voltage	0 kV



ANOMALY SUMMARY · 0 detected

No anomalies detected for this tower.

No anomalies detected for this tower.

TOWER SUMMARY · 24 OF 156

No. 0024 Healthy

BELONIA-SABROOM-T24

0 anomalies · Inspected N/A · Voltage 0 kV



Tower no	0024	Tower name	BELONIA-SABROOM-T24
Latitude	23.220938	Longitude	91.523497
X	N/A	Y	N/A
Z	253.00	Client / zone	TD_Udaipur
Inspection	N/A	Report generated	29 Sep 2026, 11:31 IST
Transmission line	SABROOM C1	Line voltage	0 kV

ANOMALY SUMMARY · 0 detected

No anomalies detected for this tower.

TRIPURA POWER TRANSMISSION LIMITED
TPTL

No anomalies detected for this tower.

TRIPURA POWER TRANSMISSION LIMITED
TPTL

No. 0025 Healthy

BELONIA-SABROOM-T25

0 anomalies · Inspected N/A · Voltage 0 kV



Tower no	0025	Tower name	BELONIA-SABROOM-T25
Latitude	23.220444	Longitude	91.526953
X	N/A	Y	N/A
Z	240.00	Client / zone	TD_Udaipur
Inspection	N/A	Report generated	29 Sep 2026, 11:31 IST
Transmission line	SABROOM C1	Line voltage	0 kV

ANOMALY SUMMARY · 0 detected

No anomalies detected for this tower.

No anomalies detected for this tower.

No. 0026 Healthy

BELONIA-SABROOM-T26

0 anomalies · Inspected N/A · Voltage 0 kV



Tower no	0026	Tower name	BELONIA-SABROOM-T26
Latitude	23.219818	Longitude	91.529956
X	N/A	Y	N/A
Z	277.00	Client / zone	TD_Udaipur
Inspection	N/A	Report generated	29 Sep 2026, 11:31 IST
Transmission line	SABROOM C1	Line voltage	0 kV

ANOMALY SUMMARY · 0 detected

No anomalies detected for this tower.

TRIPURA POWER TRANSMISSION LIMITED
TPTL

No anomalies detected for this tower.

TOWER SUMMARY · 27 OF 156

No. 0027 Healthy

BELONIA-SABROOM-T27

0 anomalies · Inspected N/A · Voltage 0 kV



Tower no	0027	Tower name	BELONIA-SABROOM-T27
Latitude	23.219495	Longitude	91.532012
X	N/A	Y	N/A
Z	312.00	Client / zone	TD_Udaipur
Inspection	N/A	Report generated	29 Sep 2026, 11:31 IST
Transmission line	SABROOM C1	Line voltage	0 kV

ANOMALY SUMMARY · 0 detected

No anomalies detected for this tower.

TRIPURA POWER TRANSMISSION LIMITED
TPTL

No anomalies detected for this tower.

No. 0028 Healthy

BELONIA-SABROOM-T28

0 anomalies · Inspected N/A · Voltage 0 kV



Tower no	0028	Tower name	BELONIA-SABROOM-T28
Latitude	23.218334	Longitude	91.534969
X	N/A	Y	N/A
Z	327.00	Client / zone	TD_Udaipur
Inspection	N/A	Report generated	29 Sep 2026, 11:31 IST
Transmission line	SABROOM C1	Line voltage	0 kV

ANOMALY SUMMARY · 0 detected

No anomalies detected for this tower.

TRIPURA POWER TRANSMISSION LIMITED
TPTL

No anomalies detected for this tower.

TRIPURA POWER TRANSMISSION LIMITED
TPTL

No. 0029 Healthy

BELONIA-SABROOM-T29

0 anomalies · Inspected N/A · Voltage 0 kV



Tower no	0029	Tower name	BELONIA-SABROOM-T29
Latitude	23.218084	Longitude	91.537985
X	N/A	Y	N/A
Z	304.00	Client / zone	TD_Udaipur
Inspection	N/A	Report generated	29 Sep 2026, 11:31 IST
Transmission line	SABROOM C1	Line voltage	0 kV

ANOMALY SUMMARY · 0 detected

No anomalies detected for this tower.

TRIPURA POWER TRANSMISSION LIMITED
TPTL

No anomalies detected for this tower.

TRIPURA POWER TRANSMISSION LIMITED
TPTL

No. 0030 Healthy

BELONIA-SABROOM-T30

0 anomalies · Inspected N/A · Voltage 0 kV



Tower no	0030	Tower name	BELONIA-SABROOM-T30
Latitude	23.217112	Longitude	91.542180
X	N/A	Y	N/A
Z	261.00	Client / zone	TD_Udaipur
Inspection	N/A	Report generated	29 Sep 2026, 11:31 IST
Transmission line	SABROOM C1	Line voltage	0 kV

ANOMALY SUMMARY · 0 detected

No anomalies detected for this tower.

No anomalies detected for this tower.

TOWER SUMMARY · 31 OF 156

No. 0031 Healthy

BELONIA-SABROOM-T31

0 anomalies · Inspected N/A · Voltage 0 kV

Tower no	0031	Tower name	BELONIA-SABROOM-T31
Latitude	23.216775	Longitude	91.544067
X	N/A	Y	N/A
Z	230.00	Client / zone	TD_Udaipur
Inspection	N/A	Report generated	29 Sep 2026, 11:31 IST
Transmission line	SABROOM C1	Line voltage	0 kV



ANOMALY SUMMARY · 0 detected

No anomalies detected for this tower.

No anomalies detected for this tower.

TRIPURA POWER TRANSMISSION LIMITED
TPTL

TOWER SUMMARY · 32 OF 156

No. 0032 Healthy

BELONIA-SABROOM-T32

0 anomalies · Inspected N/A · Voltage 0 kV



Tower no	0032	Tower name	BELONIA-SABROOM-T32
Latitude	23.216464	Longitude	91.546266
X	N/A	Y	N/A
Z	280.00	Client / zone	TD_Udaipur
Inspection	N/A	Report generated	29 Sep 2026, 11:31 IST
Transmission line	SABROOM C1	Line voltage	0 kV

ANOMALY SUMMARY · 0 detected

No anomalies detected for this tower.

TRIPURA POWER TRANSMISSION LIMITED
TPTL

No anomalies detected for this tower.

TRIPURA POWER TRANSMISSION LIMITED
TPTL

No. 0033 Healthy

BELONIA-SABROOM-T33

0 anomalies · Inspected N/A · Voltage 0 kV



Tower no	0033	Tower name	BELONIA-SABROOM-T33
Latitude	23.215294	Longitude	91.550271
X	N/A	Y	N/A
Z	210.00	Client / zone	TD_Udaipur
Inspection	N/A	Report generated	29 Sep 2026, 11:31 IST
Transmission line	SABROOM C1	Line voltage	0 kV

ANOMALY SUMMARY · 0 detected

No anomalies detected for this tower.

TRIPURA POWER TRANSMISSION LIMITED
TPTL

No anomalies detected for this tower.

TRIPURA POWER TRANSMISSION LIMITED
TPTL

TOWER SUMMARY · 34 OF 156

No. 0034 Healthy

BELONIA-SABROOM-T34

0 anomalies · Inspected N/A · Voltage 0 kV



Tower no	0034	Tower name	BELONIA-SABROOM-T34
Latitude	23.215070	Longitude	91.551738
X	N/A	Y	N/A
Z	169.00	Client / zone	TD_Udaipur
Inspection	N/A	Report generated	29 Sep 2026, 11:31 IST
Transmission line	SABROOM C1	Line voltage	0 kV

ANOMALY SUMMARY · 0 detected

No anomalies detected for this tower.

TRIPURA POWER TRANSMISSION LIMITED
TPTL

No anomalies detected for this tower.

TRIPURA POWER TRANSMISSION LIMITED
TPTL

No. 0035 Healthy

BELONIA-SABROOM-T35

0 anomalies · Inspected N/A · Voltage 0 kV



Tower no	0035	Tower name	BELONIA-SABROOM-T35
Latitude	23.215204	Longitude	91.552558
X	N/A	Y	N/A
Z	169.00	Client / zone	TD_Udaipur
Inspection	N/A	Report generated	29 Sep 2026, 11:31 IST
Transmission line	SABROOM C1	Line voltage	0 kV

ANOMALY SUMMARY · 0 detected

No anomalies detected for this tower.

TRIPURA POWER TRANSMISSION LIMITED
TPTL

No anomalies detected for this tower.

TRIPURA POWER TRANSMISSION LIMITED
TPTL

No. 0036 Healthy

BELONIA-SABROOM-T36

0 anomalies · Inspected N/A · Voltage 0 kV



Tower no	0036	Tower name	BELONIA-SABROOM-T36
Latitude	23.214469	Longitude	91.553665
X	N/A	Y	N/A
Z	177.00	Client / zone	TD_Udaipur
Inspection	N/A	Report generated	29 Sep 2026, 11:31 IST
Transmission line	SABROOM C1	Line voltage	0 kV

ANOMALY SUMMARY · 0 detected

No anomalies detected for this tower.

TRIPURA POWER TRANSMISSION LIMITED
TPTL

No anomalies detected for this tower.

TRIPURA POWER TRANSMISSION LIMITED
TPTL

No. 0037 Healthy

BELONIA-SABROOM-T37

0 anomalies · Inspected N/A · Voltage 0 kV



Tower no	0037	Tower name	BELONIA-SABROOM-T37
Latitude	23.214494	Longitude	91.555386
X	N/A	Y	N/A
Z	168.00	Client / zone	TD_Udaipur
Inspection	N/A	Report generated	29 Sep 2026, 11:31 IST
Transmission line	SABROOM C1	Line voltage	0 kV

ANOMALY SUMMARY · 0 detected

No anomalies detected for this tower.

TRIPURA POWER TRANSMISSION LIMITED
TPTL

No anomalies detected for this tower.

TOWER SUMMARY · 38 OF 156

No. 0038 Healthy

BELONIA-SABROOM-T38

0 anomalies · Inspected N/A · Voltage 0 kV



Tower no	0038	Tower name	BELONIA-SABROOM-T38
Latitude	23.213504	Longitude	91.557478
X	N/A	Y	N/A
Z	243.00	Client / zone	TD_Udaipur
Inspection	N/A	Report generated	29 Sep 2026, 11:31 IST
Transmission line	SABROOM C1	Line voltage	0 kV

ANOMALY SUMMARY · 0 detected

No anomalies detected for this tower.

TRIPURA POWER TRANSMISSION LIMITED
TPTL

No anomalies detected for this tower.

TRIPURA POWER TRANSMISSION LIMITED
TPTL

TOWER SUMMARY · 39 OF 156

No. 0039 Healthy

BELONIA-SABROOM-T39

0 anomalies · Inspected N/A · Voltage 0 kV



Tower no	0039	Tower name	BELONIA-SABROOM-T39
Latitude	23.212323	Longitude	91.559539
X	N/A	Y	N/A
Z	261.00	Client / zone	TD_Udaipur
Inspection	N/A	Report generated	29 Sep 2026, 11:31 IST
Transmission line	SABROOM C1	Line voltage	0 kV

ANOMALY SUMMARY · 0 detected

No anomalies detected for this tower.

TRIPURA POWER TRANSMISSION LIMITED
TPTL

No anomalies detected for this tower.

TRIPURA POWER TRANSMISSION LIMITED
TPTL

TOWER SUMMARY · 40 OF 156

No. 0040 Healthy

BELONIA-SABROOM-T40

0 anomalies · Inspected N/A · Voltage 0 kV



Tower no	0040	Tower name	BELONIA-SABROOM-T40
Latitude	23.211348	Longitude	91.562353
X	N/A	Y	N/A
Z	323.00	Client / zone	TD_Udaipur
Inspection	N/A	Report generated	29 Sep 2026, 11:31 IST
Transmission line	SABROOM C1	Line voltage	0 kV

ANOMALY SUMMARY · 0 detected

No anomalies detected for this tower.

TRIPURA POWER TRANSMISSION LIMITED
TPTL

No anomalies detected for this tower.

No. 0041 Healthy

BELONIA-SABROOM-T41

0 anomalies · Inspected N/A · Voltage 0 kV



Tower no	0041	Tower name	BELONIA-SABROOM-T41
Latitude	23.209976	Longitude	91.564615
X	N/A	Y	N/A
Z	191.00	Client / zone	TD_Udaipur
Inspection	N/A	Report generated	29 Sep 2026, 11:31 IST
Transmission line	SABROOM C1	Line voltage	0 kV

ANOMALY SUMMARY · 0 detected

No anomalies detected for this tower.

TRIPURA POWER TRANSMISSION LIMITED
TPTL

No anomalies detected for this tower.

No. 0042 Healthy

BELONIA-SABROOM-T42

0 anomalies · Inspected N/A · Voltage 0 kV



Tower no	0042	Tower name	BELONIA-SABROOM-T42
Latitude	23.208487	Longitude	91.567802
X	N/A	Y	N/A
Z	204.00	Client / zone	TD_Udaipur
Inspection	N/A	Report generated	29 Sep 2026, 11:31 IST
Transmission line	SABROOM C1	Line voltage	0 kV

ANOMALY SUMMARY · 0 detected

No anomalies detected for this tower.

TRIPURA POWER TRANSMISSION LIMITED
TPTL

No anomalies detected for this tower.

TRIPURA POWER TRANSMISSION LIMITED
TPTL

No. 0043 Healthy

BELONIA-SABROOM-T43

0 anomalies · Inspected N/A · Voltage 0 kV



Tower no	0043	Tower name	BELONIA-SABROOM-T43
Latitude	23.206191	Longitude	91.570563
X	N/A	Y	N/A
Z	201.00	Client / zone	TD_Udaipur
Inspection	N/A	Report generated	29 Sep 2026, 11:31 IST
Transmission line	SABROOM C1	Line voltage	0 kV

ANOMALY SUMMARY · 0 detected

No anomalies detected for this tower.

TRIPURA POWER TRANSMISSION LIMITED
TPTL

No anomalies detected for this tower.

No. 0044 Healthy

BELONIA-SABROOM-T44

0 anomalies · Inspected N/A · Voltage 0 kV



Tower no	0044	Tower name	BELONIA-SABROOM-T44
Latitude	23.203940	Longitude	91.571192
X	N/A	Y	N/A
Z	213.00	Client / zone	TD_Udaipur
Inspection	N/A	Report generated	29 Sep 2026, 11:31 IST
Transmission line	SABROOM C1	Line voltage	0 kV

ANOMALY SUMMARY · 0 detected

No anomalies detected for this tower.

TRIPURA POWER TRANSMISSION LIMITED
TPTL

No anomalies detected for this tower.

TRIPURA POWER TRANSMISSION LIMITED
TPTL

No. 0045 Healthy

BELONIA-SABROOM-T45

0 anomalies · Inspected N/A · Voltage 0 kV



Tower no	0045	Tower name	BELONIA-SABROOM-T45
Latitude	23.201543	Longitude	91.571978
X	N/A	Y	N/A
Z	185.00	Client / zone	TD_Udaipur
Inspection	N/A	Report generated	29 Sep 2026, 11:31 IST
Transmission line	SABROOM C1	Line voltage	0 kV

ANOMALY SUMMARY · 0 detected

No anomalies detected for this tower.

TRIPURA POWER TRANSMISSION LIMITED
TPTL

No anomalies detected for this tower.

No. 0046 Healthy

BELONIA-SABROOM-T46

0 anomalies · Inspected N/A · Voltage 0 kV



Tower no	0046	Tower name	BELONIA-SABROOM-T46
Latitude	23.199157	Longitude	91.572706
X	N/A	Y	N/A
Z	176.00	Client / zone	TD_Udaipur
Inspection	N/A	Report generated	29 Sep 2026, 11:31 IST
Transmission line	SABROOM C1	Line voltage	0 kV

ANOMALY SUMMARY · 0 detected

No anomalies detected for this tower.

No anomalies detected for this tower.

TRIPURA POWER TRANSMISSION LIMITED
TPTL

No. 0047 Healthy

BELONIA-SABROOM-T47

0 anomalies · Inspected N/A · Voltage 0 kV



Tower no	0047	Tower name	BELONIA-SABROOM-T47
Latitude	23.197164	Longitude	91.573318
X	N/A	Y	N/A
Z	185.00	Client / zone	TD_Udaipur
Inspection	N/A	Report generated	29 Sep 2026, 11:31 IST
Transmission line	SABROOM C1	Line voltage	0 kV

ANOMALY SUMMARY · 0 detected

No anomalies detected for this tower.

TRIPURA POWER TRANSMISSION LIMITED
TPTL

No anomalies detected for this tower.

No. 0048 Healthy

BELONIA-SABROOM-T48

0 anomalies · Inspected N/A · Voltage 0 kV



Tower no	0048	Tower name	BELONIA-SABROOM-T48
Latitude	23.194721	Longitude	91.574597
X	N/A	Y	N/A
Z	229.00	Client / zone	TD_Udaipur
Inspection	N/A	Report generated	29 Sep 2026, 11:31 IST
Transmission line	SABROOM C1	Line voltage	0 kV

ANOMALY SUMMARY · 0 detected

No anomalies detected for this tower.

TRIPURA POWER TRANSMISSION LIMITED
TPTL

No anomalies detected for this tower.

TRIPURA POWER TRANSMISSION LIMITED
TPTL

No. 0049 Healthy

BELONIA-SABROOM-T49

0 anomalies · Inspected N/A · Voltage 0 kV



Tower no	0049	Tower name	BELONIA-SABROOM-T49
Latitude	23.191535	Longitude	91.575869
X	N/A	Y	N/A
Z	216.00	Client / zone	TD_Udaipur
Inspection	N/A	Report generated	29 Sep 2026, 11:31 IST
Transmission line	SABROOM C1	Line voltage	0 kV

ANOMALY SUMMARY · 0 detected

No anomalies detected for this tower.

TRIPURA POWER TRANSMISSION LIMITED
TPTL

No anomalies detected for this tower.

TOWER SUMMARY · 50 OF 156

No. 0050 Healthy

BELONIA-SABROOM-T50

0 anomalies · Inspected N/A · Voltage 0 kV



Tower no	0050	Tower name	BELONIA-SABROOM-T50
Latitude	23.188618	Longitude	91.578001
X	N/A	Y	N/A
Z	225.00	Client / zone	TD_Udaipur
Inspection	N/A	Report generated	29 Sep 2026, 11:31 IST
Transmission line	SABROOM C1	Line voltage	0 kV

ANOMALY SUMMARY · 0 detected

No anomalies detected for this tower.

TRIPURA POWER TRANSMISSION LIMITED
TPTL

No anomalies detected for this tower.

TRIPURA POWER TRANSMISSION LIMITED
TPTL

No. 0051 Healthy

BELONIA-SABROOM-T51

0 anomalies · Inspected N/A · Voltage 0 kV



Tower no	0051	Tower name	BELONIA-SABROOM-T51
Latitude	23.186873	Longitude	91.578864
X	N/A	Y	N/A
Z	194.00	Client / zone	TD_Udaipur
Inspection	N/A	Report generated	29 Sep 2026, 11:31 IST
Transmission line	SABROOM C1	Line voltage	0 kV

ANOMALY SUMMARY · 0 detected

No anomalies detected for this tower.

TRIPURA POWER TRANSMISSION LIMITED
TPTL

No anomalies detected for this tower.

No. 0052 Healthy

BELONIA-SABROOM-T52

0 anomalies · Inspected N/A · Voltage 0 kV



Tower no	0052	Tower name	BELONIA-SABROOM-T52
Latitude	23.184998	Longitude	91.579235
X	N/A	Y	N/A
Z	185.00	Client / zone	TD_Udaipur
Inspection	N/A	Report generated	29 Sep 2026, 11:31 IST
Transmission line	SABROOM C1	Line voltage	0 kV

ANOMALY SUMMARY · 0 detected

No anomalies detected for this tower.

TRIPURA POWER TRANSMISSION LIMITED
TPTL

No anomalies detected for this tower.

No. 0053 Healthy

BELONIA-SABROOM-T53

0 anomalies · Inspected N/A · Voltage 0 kV

Tower no	0053	Tower name	BELONIA-SABROOM-T53
Latitude	23.183100	Longitude	91.579837
X	N/A	Y	N/A
Z	235.00	Client / zone	TD_Udaipur
Inspection	N/A	Report generated	29 Sep 2026, 11:31 IST
Transmission line	SABROOM C1	Line voltage	0 kV



ANOMALY SUMMARY · 0 detected

No anomalies detected for this tower.

TRIPURA POWER TRANSMISSION LIMITED
TPTL

No anomalies detected for this tower.

No. 0054 Healthy

BELONIA-SABROOM-T54

0 anomalies · Inspected N/A · Voltage 0 kV

Tower no	0054	Tower name	BELONIA-SABROOM-T54
Latitude	23.181303	Longitude	91.580391
X	N/A	Y	N/A
Z	211.00	Client / zone	TD_Udaipur
Inspection	N/A	Report generated	29 Sep 2026, 11:31 IST
Transmission line	SABROOM C1	Line voltage	0 kV



ANOMALY SUMMARY · 0 detected

No anomalies detected for this tower.

TRIPURA POWER TRANSMISSION LIMITED
TPTL

No anomalies detected for this tower.

TRIPURA POWER TRANSMISSION LIMITED
TPTL

No. 0055 Healthy

BELONIA-SABROOM-T55

0 anomalies · Inspected N/A · Voltage 0 kV

Tower no	0055	Tower name	BELONIA-SABROOM-T55
Latitude	23.179394	Longitude	91.582211
X	N/A	Y	N/A
Z	206.00	Client / zone	TD_Udaipur
Inspection	N/A	Report generated	29 Sep 2026, 11:31 IST
Transmission line	SABROOM C1	Line voltage	0 kV



ANOMALY SUMMARY · 0 detected

No anomalies detected for this tower.

TRIPURA POWER TRANSMISSION LIMITED
TPTL

No anomalies detected for this tower.

No. 0056 Healthy

BELONIA-SABROOM-T56

0 anomalies · Inspected N/A · Voltage 0 kV



Tower no	0056	Tower name	BELONIA-SABROOM-T56
Latitude	23.177674	Longitude	91.583626
X	N/A	Y	N/A
Z	189.00	Client / zone	TD_Udaipur
Inspection	N/A	Report generated	29 Sep 2026, 11:31 IST
Transmission line	SABROOM C1	Line voltage	0 kV

ANOMALY SUMMARY · 0 detected

No anomalies detected for this tower.

TRIPURA POWER TRANSMISSION LIMITED
TPTL

No anomalies detected for this tower.

No. 0057 Healthy

BELONIA-SABROOM-T57

0 anomalies · Inspected N/A · Voltage 0 kV



Tower no	0057	Tower name	BELONIA-SABROOM-T57
Latitude	23.176711	Longitude	91.584290
X	N/A	Y	N/A
Z	238.00	Client / zone	TD_Udaipur
Inspection	N/A	Report generated	29 Sep 2026, 11:31 IST
Transmission line	SABROOM C1	Line voltage	0 kV

ANOMALY SUMMARY · 0 detected

No anomalies detected for this tower.

TRIPURA POWER TRANSMISSION LIMITED
TPTL

No anomalies detected for this tower.

No. 0058 Healthy

BELONIA-SABROOM-T58

0 anomalies · Inspected N/A · Voltage 0 kV



Tower no	0058	Tower name	BELONIA-SABROOM-T58
Latitude	23.174426	Longitude	91.587176
X	N/A	Y	N/A
Z	193.00	Client / zone	TD_Udaipur
Inspection	N/A	Report generated	29 Sep 2026, 11:31 IST
Transmission line	SABROOM C1	Line voltage	0 kV

ANOMALY SUMMARY · 0 detected

No anomalies detected for this tower.

TRIPURA POWER TRANSMISSION LIMITED
TPTL

No anomalies detected for this tower.

TRIPURA POWER TRANSMISSION LIMITED
TPTL

TOWER SUMMARY · 59 OF 156

No. 0059 Healthy

BELONIA-SABROOM-T59

0 anomalies · Inspected N/A · Voltage 0 kV



Tower no	0059	Tower name	BELONIA-SABROOM-T59
Latitude	23.172340	Longitude	91.588909
X	N/A	Y	N/A
Z	216.00	Client / zone	TD_Udaipur
Inspection	N/A	Report generated	29 Sep 2026, 11:31 IST
Transmission line	SABROOM C1	Line voltage	0 kV

ANOMALY SUMMARY · 0 detected

No anomalies detected for this tower.

TRIPURA POWER TRANSMISSION LIMITED
TPTL

No anomalies detected for this tower.

TOWER SUMMARY · 60 OF 156

No. 0060 Healthy

BELONIA-SABROOM-T60

0 anomalies · Inspected N/A · Voltage 0 kV



Tower no	0060	Tower name	BELONIA-SABROOM-T60
Latitude	23.170393	Longitude	91.591778
X	N/A	Y	N/A
Z	216.00	Client / zone	TD_Udaipur
Inspection	N/A	Report generated	29 Sep 2026, 11:31 IST
Transmission line	SABROOM C1	Line voltage	0 kV

ANOMALY SUMMARY · 0 detected

No anomalies detected for this tower.

TRIPURA POWER TRANSMISSION LIMITED
TPTL

No anomalies detected for this tower.

TOWER SUMMARY · 61 OF 156

No. 0061 Healthy

BELONIA-SABROOM-T61

0 anomalies · Inspected N/A · Voltage 0 kV

Tower no	0061	Tower name	BELONIA-SABROOM-T61
Latitude	23.168772	Longitude	91.594398
X	N/A	Y	N/A
Z	202.00	Client / zone	TD_Udaipur
Inspection	N/A	Report generated	29 Sep 2026, 11:31 IST
Transmission line	SABROOM C1	Line voltage	0 kV



ANOMALY SUMMARY · 0 detected

No anomalies detected for this tower.

TRIPURA POWER TRANSMISSION LIMITED
TPTL

No anomalies detected for this tower.

No. 0062 Healthy

BELONIA-SABROOM-T62

0 anomalies · Inspected N/A · Voltage 0 kV



Tower no	0062	Tower name	BELONIA-SABROOM-T62
Latitude	23.167984	Longitude	91.594149
X	N/A	Y	N/A
Z	211.00	Client / zone	TD_Udaipur
Inspection	N/A	Report generated	29 Sep 2026, 11:31 IST
Transmission line	SABROOM C1	Line voltage	0 kV

ANOMALY SUMMARY · 0 detected

No anomalies detected for this tower.

TRIPURA POWER TRANSMISSION LIMITED
TPTL

No anomalies detected for this tower.

TOWER SUMMARY · 63 OF 156

No. 0063 Healthy

BELONIA-SABROOM-T63

0 anomalies · Inspected N/A · Voltage 0 kV



Tower no	0063	Tower name	BELONIA-SABROOM-T63
Latitude	23.164271	Longitude	91.595875
X	N/A	Y	N/A
Z	237.00	Client / zone	TD_Udaipur
Inspection	N/A	Report generated	29 Sep 2026, 11:31 IST
Transmission line	SABROOM C1	Line voltage	0 kV

ANOMALY SUMMARY · 0 detected

No anomalies detected for this tower.

TRIPURA POWER TRANSMISSION LIMITED
TPTL

No anomalies detected for this tower.

TOWER SUMMARY · 64 OF 156

No. 0064 Healthy

BELONIA-SABROOM-T64

0 anomalies · Inspected N/A · Voltage 0 kV



Tower no	0064	Tower name	BELONIA-SABROOM-T64
Latitude	23.162470	Longitude	91.596097
X	N/A	Y	N/A
Z	246.00	Client / zone	TD_Udaipur
Inspection	N/A	Report generated	29 Sep 2026, 11:31 IST
Transmission line	SABROOM C1	Line voltage	0 kV

ANOMALY SUMMARY · 0 detected

No anomalies detected for this tower.

TRIPURA POWER TRANSMISSION LIMITED
TPTL

No anomalies detected for this tower.

TRIPURA POWER TRANSMISSION LIMITED
TPTL

No. 0065 Healthy

BELONIA-SABROOM-T65

0 anomalies · Inspected N/A · Voltage 0 kV



Tower no	0065	Tower name	BELONIA-SABROOM-T65
Latitude	23.160234	Longitude	91.596515
X	N/A	Y	N/A
Z	239.00	Client / zone	TD_Udaipur
Inspection	N/A	Report generated	29 Sep 2026, 11:31 IST
Transmission line	SABROOM C1	Line voltage	0 kV

ANOMALY SUMMARY · 0 detected

No anomalies detected for this tower.

TRIPURA POWER TRANSMISSION LIMITED
TPTL

No anomalies detected for this tower.

TRIPURA POWER TRANSMISSION LIMITED
TPTL

No. 0066 Healthy

BELONIA-SABROOM-T66

0 anomalies · Inspected N/A · Voltage 0 kV



Tower no	0066	Tower name	BELONIA-SABROOM-T66
Latitude	23.157544	Longitude	91.596877
X	N/A	Y	N/A
Z	254.00	Client / zone	TD_Udaipur
Inspection	N/A	Report generated	29 Sep 2026, 11:31 IST
Transmission line	SABROOM C1	Line voltage	0 kV

ANOMALY SUMMARY · 0 detected

No anomalies detected for this tower.

No anomalies detected for this tower.

No. 0067 Healthy

BELONIA-SABROOM-T67

0 anomalies · Inspected N/A · Voltage 0 kV



Tower no	0067	Tower name	BELONIA-SABROOM-T67
Latitude	23.154294	Longitude	91.597361
X	N/A	Y	N/A
Z	265.00	Client / zone	TD_Udaipur
Inspection	N/A	Report generated	29 Sep 2026, 11:31 IST
Transmission line	SABROOM C1	Line voltage	0 kV

ANOMALY SUMMARY · 0 detected

No anomalies detected for this tower.

TRIPURA POWER TRANSMISSION LIMITED
TPTL

No anomalies detected for this tower.

No. 0068 Healthy

BELONIA-SABROOM-T68

0 anomalies · Inspected N/A · Voltage 0 kV



Tower no	0068	Tower name	BELONIA-SABROOM-T68
Latitude	23.150577	Longitude	91.597943
X	N/A	Y	N/A
Z	260.00	Client / zone	TD_Udaipur
Inspection	N/A	Report generated	29 Sep 2026, 11:31 IST
Transmission line	SABROOM C1	Line voltage	0 kV

ANOMALY SUMMARY · 0 detected

No anomalies detected for this tower.

TRIPURA POWER TRANSMISSION LIMITED
TPTL

No anomalies detected for this tower.

TRIPURA POWER TRANSMISSION LIMITED
TPTL

TOWER SUMMARY · 69 OF 156

No. 0069 Healthy

BELONIA-SABROOM-T69

0 anomalies · Inspected N/A · Voltage 0 kV



Tower no	0069	Tower name	BELONIA-SABROOM-T69
Latitude	23.149398	Longitude	91.598696
X	N/A	Y	N/A
Z	246.00	Client / zone	TD_Udaipur
Inspection	N/A	Report generated	29 Sep 2026, 11:31 IST
Transmission line	SABROOM C1	Line voltage	0 kV

ANOMALY SUMMARY · 0 detected

No anomalies detected for this tower.

TRIPURA POWER TRANSMISSION LIMITED
TPTL

No anomalies detected for this tower.

No. 0070 Healthy

BELONIA-SABROOM-T70

0 anomalies · Inspected N/A · Voltage 0 kV



Tower no	0070	Tower name	BELONIA-SABROOM-T70
Latitude	23.148096	Longitude	91.598534
X	N/A	Y	N/A
Z	249.00	Client / zone	TD_Udaipur
Inspection	N/A	Report generated	29 Sep 2026, 11:31 IST
Transmission line	SABROOM C1	Line voltage	0 kV

ANOMALY SUMMARY · 0 detected

No anomalies detected for this tower.

TRIPURA POWER TRANSMISSION LIMITED
TPTL

No anomalies detected for this tower.

No. 0071 Healthy

BELONIA-SABROOM-T71

0 anomalies · Inspected N/A · Voltage 0 kV



Tower no	0071	Tower name	BELONIA-SABROOM-T71
Latitude	23.143871	Longitude	91.599017
X	N/A	Y	N/A
Z	229.00	Client / zone	TD_Udaipur
Inspection	N/A	Report generated	29 Sep 2026, 11:31 IST
Transmission line	SABROOM C1	Line voltage	0 kV

ANOMALY SUMMARY · 0 detected

No anomalies detected for this tower.

TRIPURA POWER TRANSMISSION LIMITED
TPTL

No anomalies detected for this tower.

No. 0072 Healthy

BELONIA-SABROOM-T72

0 anomalies · Inspected N/A · Voltage 0 kV



Tower no	0072	Tower name	BELONIA-SABROOM-T72
Latitude	23.140758	Longitude	91.599717
X	N/A	Y	N/A
Z	244.00	Client / zone	TD_Udaipur
Inspection	N/A	Report generated	29 Sep 2026, 11:31 IST
Transmission line	SABROOM C1	Line voltage	0 kV

ANOMALY SUMMARY · 0 detected

No anomalies detected for this tower.

TRIPURA POWER TRANSMISSION LIMITED
TPTL

No anomalies detected for this tower.

No. 0073 Healthy

BELONIA-SABROOM-T73

0 anomalies · Inspected N/A · Voltage 0 kV



Tower no	0073	Tower name	BELONIA-SABROOM-T73
Latitude	23.137873	Longitude	91.599837
X	N/A	Y	N/A
Z	249.00	Client / zone	TD_Udaipur
Inspection	N/A	Report generated	29 Sep 2026, 11:31 IST
Transmission line	SABROOM C1	Line voltage	0 kV

ANOMALY SUMMARY · 0 detected

No anomalies detected for this tower.

TRIPURA POWER TRANSMISSION LIMITED
TPTL

No anomalies detected for this tower.

No. 0074 Healthy

BELONIA-SABROOM-T74

0 anomalies · Inspected N/A · Voltage 0 kV



Tower no	0074	Tower name	BELONIA-SABROOM-T74
Latitude	23.135395	Longitude	91.600416
X	N/A	Y	N/A
Z	244.00	Client / zone	TD_Udaipur
Inspection	N/A	Report generated	29 Sep 2026, 11:31 IST
Transmission line	SABROOM C1	Line voltage	0 kV

ANOMALY SUMMARY · 0 detected

No anomalies detected for this tower.

No anomalies detected for this tower.

TOWER SUMMARY · 75 OF 156

No. 0075 Healthy

BELONIA-SABROOM-T75

0 anomalies · Inspected N/A · Voltage 0 kV



Tower no	0075	Tower name	BELONIA-SABROOM-T75
Latitude	23.133154	Longitude	91.600764
X	N/A	Y	N/A
Z	240.00	Client / zone	TD_Udaipur
Inspection	N/A	Report generated	29 Sep 2026, 11:31 IST
Transmission line	SABROOM C1	Line voltage	0 kV

ANOMALY SUMMARY · 0 detected

No anomalies detected for this tower.

TRIPURA POWER TRANSMISSION LIMITED
TPTL

No anomalies detected for this tower.

TOWER SUMMARY · 76 OF 156

No. 0076 Healthy

BELONIA-SABROOM-T76

0 anomalies · Inspected N/A · Voltage 0 kV



Tower no	0076	Tower name	BELONIA-SABROOM-T76
Latitude	23.131210	Longitude	91.602227
X	N/A	Y	N/A
Z	214.00	Client / zone	TD_Udaipur
Inspection	N/A	Report generated	29 Sep 2026, 11:31 IST
Transmission line	SABROOM C1	Line voltage	0 kV

ANOMALY SUMMARY · 0 detected

No anomalies detected for this tower.

TRIPURA POWER TRANSMISSION LIMITED
TPTL

No anomalies detected for this tower.

No. 0077 Healthy

BELONIA-SABROOM-T77

0 anomalies · Inspected N/A · Voltage 0 kV



Tower no	0077	Tower name	BELONIA-SABROOM-T77
Latitude	23.128891	Longitude	91.603935
X	N/A	Y	N/A
Z	209.00	Client / zone	TD_Udaipur
Inspection	N/A	Report generated	29 Sep 2026, 11:31 IST
Transmission line	SABROOM C1	Line voltage	0 kV

ANOMALY SUMMARY · 0 detected

No anomalies detected for this tower.

TRIPURA POWER TRANSMISSION LIMITED
TPTL

No anomalies detected for this tower.

No. 0078 Healthy

BELONIA-SABROOM-T78

0 anomalies · Inspected N/A · Voltage 0 kV



Tower no	0078	Tower name	BELONIA-SABROOM-T78
Latitude	23.126491	Longitude	91.603263
X	N/A	Y	N/A
Z	234.00	Client / zone	TD_Udaipur
Inspection	N/A	Report generated	29 Sep 2026, 11:31 IST
Transmission line	SABROOM C1	Line voltage	0 kV

ANOMALY SUMMARY · 0 detected

No anomalies detected for this tower.

TRIPURA POWER TRANSMISSION LIMITED
TPTL

No anomalies detected for this tower.

TRIPURA POWER TRANSMISSION LIMITED
TPTL

No. 0079 Healthy

BELONIA-SABROOM-T79

0 anomalies · Inspected N/A · Voltage 0 kV



Tower no	0079	Tower name	BELONIA-SABROOM-T79
Latitude	23.124583	Longitude	91.602549
X	N/A	Y	N/A
Z	268.00	Client / zone	TD_Udaipur
Inspection	N/A	Report generated	29 Sep 2026, 11:31 IST
Transmission line	SABROOM C1	Line voltage	0 kV

ANOMALY SUMMARY · 0 detected

No anomalies detected for this tower.

TRIPURA POWER TRANSMISSION LIMITED
TPTL

No anomalies detected for this tower.

No. 0080 Healthy

BELONIA-SABROOM-T80

0 anomalies · Inspected N/A · Voltage 0 kV



Tower no	0080	Tower name	BELONIA-SABROOM-T80
Latitude	23.122427	Longitude	91.602998
X	N/A	Y	N/A
Z	241.00	Client / zone	TD_Udaipur
Inspection	N/A	Report generated	29 Sep 2026, 11:31 IST
Transmission line	SABROOM C1	Line voltage	0 kV

ANOMALY SUMMARY · 0 detected

No anomalies detected for this tower.

TRIPURA POWER TRANSMISSION LIMITED
TPTL

No anomalies detected for this tower.

No. 0081 Healthy

BELONIA-SABROOM-T81

0 anomalies · Inspected N/A · Voltage 0 kV



Tower no	0081	Tower name	BELONIA-SABROOM-T81
Latitude	23.120390	Longitude	91.603387
X	N/A	Y	N/A
Z	264.00	Client / zone	TD_Udaipur
Inspection	N/A	Report generated	29 Sep 2026, 11:31 IST
Transmission line	SABROOM C1	Line voltage	0 kV

ANOMALY SUMMARY · 0 detected

No anomalies detected for this tower.

No anomalies detected for this tower.

No. 0082 Healthy

BELONIA-SABROOM-T82

0 anomalies · Inspected N/A · Voltage 0 kV



Tower no	0082	Tower name	BELONIA-SABROOM-T82
Latitude	23.118040	Longitude	91.603823
X	N/A	Y	N/A
Z	260.00	Client / zone	TD_Udaipur
Inspection	N/A	Report generated	29 Sep 2026, 11:31 IST
Transmission line	SABROOM C1	Line voltage	0 kV

ANOMALY SUMMARY · 0 detected

No anomalies detected for this tower.

TRIPURA POWER TRANSMISSION LIMITED
TPTL

No anomalies detected for this tower.

TRIPURA POWER TRANSMISSION LIMITED
TPTL

No. 0083 Healthy

BELONIA-SABROOM-T83

0 anomalies · Inspected N/A · Voltage 0 kV



Tower no	0083	Tower name	BELONIA-SABROOM-T83
Latitude	23.115978	Longitude	91.604295
X	N/A	Y	N/A
Z	233.00	Client / zone	TD_Udaipur
Inspection	N/A	Report generated	29 Sep 2026, 11:31 IST
Transmission line	SABROOM C1	Line voltage	0 kV

ANOMALY SUMMARY · 0 detected

No anomalies detected for this tower.

TRIPURA POWER TRANSMISSION LIMITED
TPTL

No anomalies detected for this tower.

TRIPURA POWER TRANSMISSION LIMITED
TPTL

No. 0084 Healthy

BELONIA-SABROOM-T84

0 anomalies · Inspected N/A · Voltage 0 kV



Tower no	0084	Tower name	BELONIA-SABROOM-T84
Latitude	23.114243	Longitude	91.605919
X	N/A	Y	N/A
Z	195.00	Client / zone	TD_Udaipur
Inspection	N/A	Report generated	29 Sep 2026, 11:31 IST
Transmission line	SABROOM C1	Line voltage	0 kV

ANOMALY SUMMARY · 0 detected

No anomalies detected for this tower.

TRIPURA POWER TRANSMISSION LIMITED
TPTL

No anomalies detected for this tower.

TRIPURA POWER TRANSMISSION LIMITED
TPTL

No. 0085 Healthy

BELONIA-SABROOM-T85

0 anomalies · Inspected N/A · Voltage 0 kV



Tower no	0085	Tower name	BELONIA-SABROOM-T85
Latitude	23.112650	Longitude	91.606563
X	N/A	Y	N/A
Z	202.00	Client / zone	TD_Udaipur
Inspection	N/A	Report generated	29 Sep 2026, 11:31 IST
Transmission line	SABROOM C1	Line voltage	0 kV

ANOMALY SUMMARY · 0 detected

No anomalies detected for this tower.

TRIPURA POWER TRANSMISSION LIMITED
TPTL

No anomalies detected for this tower.

TRIPURA POWER TRANSMISSION LIMITED
TPTL

No. 0086 Healthy

BELONIA-SABROOM-T86

0 anomalies · Inspected N/A · Voltage 0 kV



Tower no	0086	Tower name	BELONIA-SABROOM-T86
Latitude	23.111464	Longitude	91.607693
X	N/A	Y	N/A
Z	191.00	Client / zone	TD_Udaipur
Inspection	N/A	Report generated	29 Sep 2026, 11:31 IST
Transmission line	SABROOM C1	Line voltage	0 kV

ANOMALY SUMMARY · 0 detected

No anomalies detected for this tower.

TRIPURA POWER TRANSMISSION LIMITED
TPTL

No anomalies detected for this tower.

No. 0087 Healthy

BELONIA-SABROOM-T87

0 anomalies · Inspected N/A · Voltage 0 kV



Tower no	0087	Tower name	BELONIA-SABROOM-T87
Latitude	23.109133	Longitude	91.607984
X	N/A	Y	N/A
Z	190.00	Client / zone	TD_Udaipur
Inspection	N/A	Report generated	29 Sep 2026, 11:31 IST
Transmission line	SABROOM C1	Line voltage	0 kV

ANOMALY SUMMARY · 0 detected

No anomalies detected for this tower.

TRIPURA POWER TRANSMISSION LIMITED
TPTL

No anomalies detected for this tower.

TRIPURA POWER TRANSMISSION LIMITED
TPTL

No. 0088 Healthy

BELONIA-SABROOM-T88

0 anomalies · Inspected N/A · Voltage 0 kV



Tower no	0088	Tower name	BELONIA-SABROOM-T88
Latitude	23.107290	Longitude	91.608483
X	N/A	Y	N/A
Z	181.00	Client / zone	TD_Udaipur
Inspection	N/A	Report generated	29 Sep 2026, 11:31 IST
Transmission line	SABROOM C1	Line voltage	0 kV

ANOMALY SUMMARY · 0 detected

No anomalies detected for this tower.

TRIPURA POWER TRANSMISSION LIMITED
TPTL

No anomalies detected for this tower.

TRIPURA POWER TRANSMISSION LIMITED
TPTL

No. 0089 Healthy

BELONIA-SABROOM-T89

0 anomalies · Inspected N/A · Voltage 0 kV



Tower no	0089	Tower name	BELONIA-SABROOM-T89
Latitude	23.104346	Longitude	91.609271
X	N/A	Y	N/A
Z	214.00	Client / zone	TD_Udaipur
Inspection	N/A	Report generated	29 Sep 2026, 11:31 IST
Transmission line	SABROOM C1	Line voltage	0 kV

ANOMALY SUMMARY · 0 detected

No anomalies detected for this tower.

TRIPURA POWER TRANSMISSION LIMITED
TPTL

No anomalies detected for this tower.

TRIPURA POWER TRANSMISSION LIMITED
TPTL

No. 0090 Healthy

BELONIA-SABROOM-T90

0 anomalies · Inspected N/A · Voltage 0 kV



Tower no	0090	Tower name	BELONIA-SABROOM-T90
Latitude	23.101782	Longitude	91.610386
X	N/A	Y	N/A
Z	194.00	Client / zone	TD_Udaipur
Inspection	N/A	Report generated	29 Sep 2026, 11:31 IST
Transmission line	SABROOM C1	Line voltage	0 kV

ANOMALY SUMMARY · 0 detected

No anomalies detected for this tower.

No anomalies detected for this tower.

TRIPURA POWER TRANSMISSION LIMITED
TPTL

No. 0091 Healthy

BELONIA-SABROOM-T91

0 anomalies · Inspected N/A · Voltage 0 kV



Tower no	0091	Tower name	BELONIA-SABROOM-T91
Latitude	23.100717	Longitude	91.612715
X	N/A	Y	N/A
Z	173.00	Client / zone	TD_Udaipur
Inspection	N/A	Report generated	29 Sep 2026, 11:31 IST
Transmission line	SABROOM C1	Line voltage	0 kV

ANOMALY SUMMARY · 0 detected

No anomalies detected for this tower.

TRIPURA POWER TRANSMISSION LIMITED
TPTL

No anomalies detected for this tower.

No. 0092 Healthy

BELONIA-SABROOM-T92

0 anomalies · Inspected N/A · Voltage 0 kV



Tower no	0092	Tower name	BELONIA-SABROOM-T92
Latitude	23.098200	Longitude	91.614241
X	N/A	Y	N/A
Z	178.00	Client / zone	TD_Udaipur
Inspection	N/A	Report generated	29 Sep 2026, 11:31 IST
Transmission line	SABROOM C1	Line voltage	0 kV

ANOMALY SUMMARY · 0 detected

No anomalies detected for this tower.

TRIPURA POWER TRANSMISSION LIMITED
TPTL

No anomalies detected for this tower.

No. 0093 Healthy

BELONIA-SABROOM-T93

0 anomalies · Inspected N/A · Voltage 0 kV



Tower no	0093	Tower name	BELONIA-SABROOM-T93
Latitude	23.096037	Longitude	91.615415
X	N/A	Y	N/A
Z	209.00	Client / zone	TD_Udaipur
Inspection	N/A	Report generated	29 Sep 2026, 11:31 IST
Transmission line	SABROOM C1	Line voltage	0 kV

ANOMALY SUMMARY · 0 detected

No anomalies detected for this tower.

TRIPURA POWER TRANSMISSION LIMITED
TPTL

No anomalies detected for this tower.

No. 0094 Healthy

BELONIA-SABROOM-T94

0 anomalies · Inspected N/A · Voltage 0 kV



Tower no	0094	Tower name	BELONIA-SABROOM-T94
Latitude	23.093098	Longitude	91.616914
X	N/A	Y	N/A
Z	209.00	Client / zone	TD_Udaipur
Inspection	N/A	Report generated	29 Sep 2026, 11:31 IST
Transmission line	SABROOM C1	Line voltage	0 kV

ANOMALY SUMMARY · 0 detected

No anomalies detected for this tower.

TRIPURA POWER TRANSMISSION LIMITED
TPTL

No anomalies detected for this tower.

No. 0095 Healthy

BELONIA-SABROOM-T95

0 anomalies · Inspected N/A · Voltage 0 kV



Tower no	0095	Tower name	BELONIA-SABROOM-T95
Latitude	23.091026	Longitude	91.618225
X	N/A	Y	N/A
Z	178.00	Client / zone	TD_Udaipur
Inspection	N/A	Report generated	29 Sep 2026, 11:31 IST
Transmission line	SABROOM C1	Line voltage	0 kV

ANOMALY SUMMARY · 0 detected

No anomalies detected for this tower.

TRIPURA POWER TRANSMISSION LIMITED
TPTL

No anomalies detected for this tower.

TRIPURA POWER TRANSMISSION LIMITED
TPTL

TOWER SUMMARY · 96 OF 156

No. 0096 Healthy

BELONIA-SABROOM-T96

0 anomalies · Inspected N/A · Voltage 0 kV



Tower no	0096	Tower name	BELONIA-SABROOM-T96
Latitude	23.089326	Longitude	91.619198
X	N/A	Y	N/A
Z	237.00	Client / zone	TD_Udaipur
Inspection	N/A	Report generated	29 Sep 2026, 11:31 IST
Transmission line	SABROOM C1	Line voltage	0 kV

ANOMALY SUMMARY · 0 detected

No anomalies detected for this tower.

TRIPURA POWER TRANSMISSION LIMITED
TPTL

No anomalies detected for this tower.

TRIPURA POWER TRANSMISSION LIMITED
TPTL

No. 0097 Healthy

BELONIA-SABROOM-T97

0 anomalies · Inspected N/A · Voltage 0 kV



Tower no	0097	Tower name	BELONIA-SABROOM-T97
Latitude	23.087099	Longitude	91.620725
X	N/A	Y	N/A
Z	222.00	Client / zone	TD_Udaipur
Inspection	N/A	Report generated	29 Sep 2026, 11:31 IST
Transmission line	SABROOM C1	Line voltage	0 kV

ANOMALY SUMMARY · 0 detected

No anomalies detected for this tower.

TRIPURA POWER TRANSMISSION LIMITED
TPTL

No anomalies detected for this tower.

TRIPURA POWER TRANSMISSION LIMITED
TPTL

No. 0098 Healthy

BELONIA-SABROOM-T98

0 anomalies · Inspected N/A · Voltage 0 kV



Tower no	0098	Tower name	BELONIA-SABROOM-T98
Latitude	23.083773	Longitude	91.622329
X	N/A	Y	N/A
Z	189.00	Client / zone	TD_Udaipur
Inspection	N/A	Report generated	29 Sep 2026, 11:31 IST
Transmission line	SABROOM C1	Line voltage	0 kV

ANOMALY SUMMARY · 0 detected

No anomalies detected for this tower.

TRIPURA POWER TRANSMISSION LIMITED
TPTL

No anomalies detected for this tower.

No. 0099 Healthy

BELONIA-SABROOM-T99

0 anomalies · Inspected N/A · Voltage 0 kV



Tower no	0099	Tower name	BELONIA-SABROOM-T99
Latitude	23.082055	Longitude	91.623482
X	N/A	Y	N/A
Z	201.00	Client / zone	TD_Udaipur
Inspection	N/A	Report generated	29 Sep 2026, 11:31 IST
Transmission line	SABROOM C1	Line voltage	0 kV

ANOMALY SUMMARY · 0 detected

No anomalies detected for this tower.

TRIPURA POWER TRANSMISSION LIMITED
TPTL

No anomalies detected for this tower.

TRIPURA POWER TRANSMISSION LIMITED
TPTL

No. 0100 Healthy

BELONIA-SABROOM-T100

0 anomalies · Inspected N/A · Voltage 0 kV



Tower no	0100	Tower name	BELONIA-SABROOM-T100
Latitude	23.079684	Longitude	91.624896
X	N/A	Y	N/A
Z	228.00	Client / zone	TD_Udaipur
Inspection	N/A	Report generated	29 Sep 2026, 11:31 IST
Transmission line	SABROOM C1	Line voltage	0 kV

ANOMALY SUMMARY · 0 detected

No anomalies detected for this tower.

TRIPURA POWER TRANSMISSION LIMITED
TPTL

No anomalies detected for this tower.

TRIPURA POWER TRANSMISSION LIMITED
TPTL

No. 0101 Healthy

BELONIA-SABROOM-T101

0 anomalies · Inspected N/A · Voltage 0 kV



Tower no	0101	Tower name	BELONIA-SABROOM-T101
Latitude	23.078544	Longitude	91.625667
X	N/A	Y	N/A
Z	225.00	Client / zone	TD_Udaipur
Inspection	N/A	Report generated	29 Sep 2026, 11:31 IST
Transmission line	SABROOM C1	Line voltage	0 kV

ANOMALY SUMMARY · 0 detected

No anomalies detected for this tower.

TRIPURA POWER TRANSMISSION LIMITED
TPTL

No anomalies detected for this tower.

No. 0102 Healthy

BELONIA-SABROOM-T102

0 anomalies · Inspected N/A · Voltage 0 kV



Tower no	0102	Tower name	BELONIA-SABROOM-T102
Latitude	23.077213	Longitude	91.626154
X	N/A	Y	N/A
Z	183.00	Client / zone	TD_Udaipur
Inspection	N/A	Report generated	29 Sep 2026, 11:31 IST
Transmission line	SABROOM C1	Line voltage	0 kV

ANOMALY SUMMARY · 0 detected

No anomalies detected for this tower.

No anomalies detected for this tower.

No. 0103 Healthy

BELONIA-SABROOM-T103

0 anomalies · Inspected N/A · Voltage 0 kV



Tower no	0103	Tower name	BELONIA-SABROOM-T103
Latitude	23.076389	Longitude	91.626893
X	N/A	Y	N/A
Z	169.00	Client / zone	TD_Udaipur
Inspection	N/A	Report generated	29 Sep 2026, 11:31 IST
Transmission line	SABROOM C1	Line voltage	0 kV

ANOMALY SUMMARY · 0 detected

No anomalies detected for this tower.

TRIPURA POWER TRANSMISSION LIMITED
TPTL

No anomalies detected for this tower.

TRIPURA POWER TRANSMISSION LIMITED
TPTL

No. 0104 Healthy

BELONIA-SABROOM-T104

0 anomalies · Inspected N/A · Voltage 0 kV



Tower no	0104	Tower name	BELONIA-SABROOM-T104
Latitude	23.074332	Longitude	91.628347
X	N/A	Y	N/A
Z	165.00	Client / zone	TD_Udaipur
Inspection	N/A	Report generated	29 Sep 2026, 11:31 IST
Transmission line	SABROOM C1	Line voltage	0 kV

ANOMALY SUMMARY · 0 detected

No anomalies detected for this tower.

TRIPURA POWER TRANSMISSION LIMITED
TPTL

No anomalies detected for this tower.

No. 0105 Healthy

BELONIA-SABROOM-T105

0 anomalies · Inspected N/A · Voltage 0 kV

Tower no	0105	Tower name	BELONIA-SABROOM-T105
Latitude	23.072215	Longitude	91.629615
X	N/A	Y	N/A
Z	180.00	Client / zone	TD_Udaipur
Inspection	N/A	Report generated	29 Sep 2026, 11:31 IST
Transmission line	SABROOM C1	Line voltage	0 kV



ANOMALY SUMMARY · 0 detected

No anomalies detected for this tower.

No anomalies detected for this tower.

No. 0106 Healthy

BELONIA-SABROOM-T106

0 anomalies · Inspected N/A · Voltage 0 kV



Tower no	0106	Tower name	BELONIA-SABROOM-T106
Latitude	23.069070	Longitude	91.631505
X	N/A	Y	N/A
Z	196.00	Client / zone	TD_Udaipur
Inspection	N/A	Report generated	29 Sep 2026, 11:31 IST
Transmission line	SABROOM C1	Line voltage	0 kV

ANOMALY SUMMARY · 0 detected

No anomalies detected for this tower.

TRIPURA POWER TRANSMISSION LIMITED
TPTL

No anomalies detected for this tower.

TRIPURA POWER TRANSMISSION LIMITED
TPTL

No. 0107 Healthy

BELONIA-SABROOM-T107

0 anomalies · Inspected N/A · Voltage 0 kV



Tower no	0107	Tower name	BELONIA-SABROOM-T107
Latitude	23.067341	Longitude	91.632151
X	N/A	Y	N/A
Z	161.00	Client / zone	TD_Udaipur
Inspection	N/A	Report generated	29 Sep 2026, 11:31 IST
Transmission line	SABROOM C1	Line voltage	0 kV

ANOMALY SUMMARY · 0 detected

No anomalies detected for this tower.

TRIPURA POWER TRANSMISSION LIMITED
TPTL

No anomalies detected for this tower.

No. 0108 Healthy

BELONIA-SABROOM-T108

0 anomalies · Inspected N/A · Voltage 0 kV



Tower no	0108	Tower name	BELONIA-SABROOM-T108
Latitude	23.065975	Longitude	91.633856
X	N/A	Y	N/A
Z	234.00	Client / zone	TD_Udaipur
Inspection	N/A	Report generated	29 Sep 2026, 11:31 IST
Transmission line	SABROOM C1	Line voltage	0 kV

ANOMALY SUMMARY · 0 detected

No anomalies detected for this tower.

TRIPURA POWER TRANSMISSION LIMITED
TPTL

No anomalies detected for this tower.

No. 0109 Healthy

BELONIA-SABROOM-T109

0 anomalies · Inspected N/A · Voltage 0 kV



Tower no	0109	Tower name	BELONIA-SABROOM-T109
Latitude	23.063884	Longitude	91.634025
X	N/A	Y	N/A
Z	200.00	Client / zone	TD_Udaipur
Inspection	N/A	Report generated	29 Sep 2026, 11:31 IST
Transmission line	SABROOM C1	Line voltage	0 kV

ANOMALY SUMMARY · 0 detected

No anomalies detected for this tower.

TRIPURA POWER TRANSMISSION LIMITED
TPTL

No anomalies detected for this tower.

No. 0110 Healthy

BELONIA-SABROOM-T110

0 anomalies · Inspected N/A · Voltage 0 kV



Tower no	0110	Tower name	BELONIA-SABROOM-T110
Latitude	23.062588	Longitude	91.634536
X	N/A	Y	N/A
Z	198.00	Client / zone	TD_Udaipur
Inspection	N/A	Report generated	29 Sep 2026, 11:31 IST
Transmission line	SABROOM C1	Line voltage	0 kV

ANOMALY SUMMARY · 0 detected

No anomalies detected for this tower.

No anomalies detected for this tower.

No. 0111 Healthy

BELONIA-SABROOM-T111

0 anomalies · Inspected N/A · Voltage 0 kV



Tower no	0111	Tower name	BELONIA-SABROOM-T111
Latitude	23.059463	Longitude	91.635700
X	N/A	Y	N/A
Z	194.00	Client / zone	TD_Udaipur
Inspection	N/A	Report generated	29 Sep 2026, 11:31 IST
Transmission line	SABROOM C1	Line voltage	0 kV

ANOMALY SUMMARY · 0 detected

No anomalies detected for this tower.

TRIPURA POWER TRANSMISSION LIMITED
TPTL

No anomalies detected for this tower.

No. 0112 Healthy

BELONIA-SABROOM-T112

0 anomalies · Inspected N/A · Voltage 0 kV



Tower no	0112	Tower name	BELONIA-SABROOM-T112
Latitude	23.056757	Longitude	91.636805
X	N/A	Y	N/A
Z	208.00	Client / zone	TD_Udaipur
Inspection	N/A	Report generated	29 Sep 2026, 11:31 IST
Transmission line	SABROOM C1	Line voltage	0 kV

ANOMALY SUMMARY · 0 detected

No anomalies detected for this tower.

TRIPURA POWER TRANSMISSION LIMITED
TPTL

No anomalies detected for this tower.

No. 0113 Healthy

BELONIA-SABROOM-T113

0 anomalies · Inspected N/A · Voltage 0 kV



Tower no	0113	Tower name	BELONIA-SABROOM-T113
Latitude	23.055908	Longitude	91.637250
X	N/A	Y	N/A
Z	163.00	Client / zone	TD_Udaipur
Inspection	N/A	Report generated	29 Sep 2026, 11:31 IST
Transmission line	SABROOM C1	Line voltage	0 kV

ANOMALY SUMMARY · 0 detected

No anomalies detected for this tower.

TRIPURA POWER TRANSMISSION LIMITED
TPTL

No anomalies detected for this tower.

No. 0114 Healthy

BELONIA-SABROOM-T114

0 anomalies · Inspected N/A · Voltage 0 kV



Tower no	0114	Tower name	BELONIA-SABROOM-T114
Latitude	23.054012	Longitude	91.637937
X	N/A	Y	N/A
Z	162.00	Client / zone	TD_Udaipur
Inspection	N/A	Report generated	29 Sep 2026, 11:31 IST
Transmission line	SABROOM C1	Line voltage	0 kV

ANOMALY SUMMARY · 0 detected

No anomalies detected for this tower.

TRIPURA POWER TRANSMISSION LIMITED
TPTL

No anomalies detected for this tower.

No. 0115 Healthy

BELONIA-SABROOM-T115

0 anomalies · Inspected N/A · Voltage 0 kV



Tower no	0115	Tower name	BELONIA-SABROOM-T115
Latitude	23.052243	Longitude	91.638633
X	N/A	Y	N/A
Z	186.00	Client / zone	TD_Udaipur
Inspection	N/A	Report generated	29 Sep 2026, 11:31 IST
Transmission line	SABROOM C1	Line voltage	0 kV

ANOMALY SUMMARY · 0 detected

No anomalies detected for this tower.

TRIPURA POWER TRANSMISSION LIMITED
TPTL

No anomalies detected for this tower.

TRIPURA POWER TRANSMISSION LIMITED
TPTL

No. 0116 Healthy

BELONIA-SABROOM-T116

0 anomalies · Inspected N/A · Voltage 0 kV



Tower no	0116	Tower name	BELONIA-SABROOM-T116
Latitude	23.049841	Longitude	91.639487
X	N/A	Y	N/A
Z	228.00	Client / zone	TD_Udaipur
Inspection	N/A	Report generated	29 Sep 2026, 11:31 IST
Transmission line	SABROOM C1	Line voltage	0 kV

ANOMALY SUMMARY · 0 detected

No anomalies detected for this tower.

TRIPURA POWER TRANSMISSION LIMITED
TPTL

No anomalies detected for this tower.

TRIPURA POWER TRANSMISSION LIMITED
TPTL

No. 0117 Healthy

BELONIA-SABROOM-T117

0 anomalies · Inspected N/A · Voltage 0 kV



Tower no	0117	Tower name	BELONIA-SABROOM-T117
Latitude	23.046978	Longitude	91.641167
X	N/A	Y	N/A
Z	194.00	Client / zone	TD_Udaipur
Inspection	N/A	Report generated	29 Sep 2026, 11:31 IST
Transmission line	SABROOM C1	Line voltage	0 kV

ANOMALY SUMMARY · 0 detected

No anomalies detected for this tower.

TRIPURA POWER TRANSMISSION LIMITED
TPTL

No anomalies detected for this tower.

TRIPURA POWER TRANSMISSION LIMITED
TPTL

No. 0118 Healthy

BELONIA-SABROOM-T118

0 anomalies · Inspected N/A · Voltage 0 kV



Tower no	0118	Tower name	BELONIA-SABROOM-T118
Latitude	23.044863	Longitude	91.642374
X	N/A	Y	N/A
Z	156.00	Client / zone	TD_Udaipur
Inspection	N/A	Report generated	29 Sep 2026, 11:31 IST
Transmission line	SABROOM C1	Line voltage	0 kV

ANOMALY SUMMARY · 0 detected

No anomalies detected for this tower.

TRIPURA POWER TRANSMISSION LIMITED
TPTL

No anomalies detected for this tower.

TRIPURA POWER TRANSMISSION LIMITED
TPTL

No. 0119 Healthy

BELONIA-SABROOM-T119

0 anomalies · Inspected N/A · Voltage 0 kV



Tower no	0119	Tower name	BELONIA-SABROOM-T119
Latitude	23.043921	Longitude	91.645542
X	N/A	Y	N/A
Z	162.00	Client / zone	TD_Udaipur
Inspection	N/A	Report generated	29 Sep 2026, 11:31 IST
Transmission line	SABROOM C1	Line voltage	0 kV

ANOMALY SUMMARY · 0 detected

No anomalies detected for this tower.

TRIPURA POWER TRANSMISSION LIMITED
TPTL

No anomalies detected for this tower.

TOWER SUMMARY · 120 OF 156

No. 0120 Healthy

BELONIA-SABROOM-T120

0 anomalies · Inspected N/A · Voltage 0 kV



Tower no	0120	Tower name	BELONIA-SABROOM-T120
Latitude	23.043018	Longitude	91.647483
X	N/A	Y	N/A
Z	149.00	Client / zone	TD_Udaipur
Inspection	N/A	Report generated	29 Sep 2026, 11:31 IST
Transmission line	SABROOM C1	Line voltage	0 kV

ANOMALY SUMMARY · 0 detected

No anomalies detected for this tower.

TRIPURA POWER TRANSMISSION LIMITED
TPTL

No anomalies detected for this tower.

No. 0121 Healthy

BELONIA-SABROOM-T121

0 anomalies · Inspected N/A · Voltage 0 kV



Tower no	0121	Tower name	BELONIA-SABROOM-T121
Latitude	23.042075	Longitude	91.649418
X	N/A	Y	N/A
Z	200.00	Client / zone	TD_Udaipur
Inspection	N/A	Report generated	29 Sep 2026, 11:31 IST
Transmission line	SABROOM C1	Line voltage	0 kV

ANOMALY SUMMARY · 0 detected

No anomalies detected for this tower.

TRIPURA POWER TRANSMISSION LIMITED
TPTL

No anomalies detected for this tower.

No. 0122 Healthy

BELONIA-SABROOM-T122

0 anomalies · Inspected N/A · Voltage 0 kV



Tower no	0122	Tower name	BELONIA-SABROOM-T122
Latitude	23.040733	Longitude	91.651923
X	N/A	Y	N/A
Z	190.00	Client / zone	TD_Udaipur
Inspection	N/A	Report generated	29 Sep 2026, 11:31 IST
Transmission line	SABROOM C1	Line voltage	0 kV

ANOMALY SUMMARY · 0 detected

No anomalies detected for this tower.

TRIPURA POWER TRANSMISSION LIMITED
TPTL

No anomalies detected for this tower.

No. 0123 Healthy

BELONIA-SABROOM-T123

0 anomalies · Inspected N/A · Voltage 0 kV



Tower no	0123	Tower name	BELONIA-SABROOM-T123
Latitude	23.039600	Longitude	91.653528
X	N/A	Y	N/A
Z	167.00	Client / zone	TD_Udaipur
Inspection	N/A	Report generated	29 Sep 2026, 11:31 IST
Transmission line	SABROOM C1	Line voltage	0 kV

ANOMALY SUMMARY · 0 detected

No anomalies detected for this tower.

TRIPURA POWER TRANSMISSION LIMITED
TPTL

No anomalies detected for this tower.

TOWER SUMMARY · 124 OF 156

No. 0124 Healthy

BELONIA-SABROOM-T124

0 anomalies · Inspected N/A · Voltage 0 kV



Tower no	0124	Tower name	BELONIA-SABROOM-T124
Latitude	23.038936	Longitude	91.655020
X	N/A	Y	N/A
Z	164.00	Client / zone	TD_Udaipur
Inspection	N/A	Report generated	29 Sep 2026, 11:31 IST
Transmission line	SABROOM C1	Line voltage	0 kV

ANOMALY SUMMARY · 0 detected

No anomalies detected for this tower.

TRIPURA POWER TRANSMISSION LIMITED
TPTL

No anomalies detected for this tower.

TRIPURA POWER TRANSMISSION LIMITED
TPTL

No. 0125 Healthy

BELONIA-SABROOM-T125

0 anomalies · Inspected N/A · Voltage 0 kV



Tower no	0125	Tower name	BELONIA-SABROOM-T125
Latitude	23.038317	Longitude	91.655869
X	N/A	Y	N/A
Z	172.00	Client / zone	TD_Udaipur
Inspection	N/A	Report generated	29 Sep 2026, 11:31 IST
Transmission line	SABROOM C1	Line voltage	0 kV

ANOMALY SUMMARY · 0 detected

No anomalies detected for this tower.

TRIPURA POWER TRANSMISSION LIMITED
TPTL

No anomalies detected for this tower.

No. 0126 Healthy

BELONIA-SABROOM-T126

0 anomalies · Inspected N/A · Voltage 0 kV



Tower no	0126	Tower name	BELONIA-SABROOM-T126
Latitude	23.037736	Longitude	91.656908
X	N/A	Y	N/A
Z	170.00	Client / zone	TD_Udaipur
Inspection	N/A	Report generated	29 Sep 2026, 11:31 IST
Transmission line	SABROOM C1	Line voltage	0 kV

ANOMALY SUMMARY · 0 detected

No anomalies detected for this tower.

TRIPURA POWER TRANSMISSION LIMITED
TPTL

No anomalies detected for this tower.

TRIPURA POWER TRANSMISSION LIMITED
TPTL

No. 0127 Healthy

BELONIA-SABROOM-T127

0 anomalies · Inspected N/A · Voltage 0 kV



Tower no	0127	Tower name	BELONIA-SABROOM-T127
Latitude	23.037030	Longitude	91.657083
X	N/A	Y	N/A
Z	177.00	Client / zone	TD_Udaipur
Inspection	N/A	Report generated	29 Sep 2026, 11:31 IST
Transmission line	SABROOM C1	Line voltage	0 kV

ANOMALY SUMMARY · 0 detected

No anomalies detected for this tower.

TRIPURA POWER TRANSMISSION LIMITED
TPTL

No anomalies detected for this tower.

No. 0128 Healthy

BELONIA-SABROOM-T128

0 anomalies · Inspected N/A · Voltage 0 kV



Tower no	0128	Tower name	BELONIA-SABROOM-T128
Latitude	23.036689	Longitude	91.658181
X	N/A	Y	N/A
Z	156.00	Client / zone	TD_Udaipur
Inspection	N/A	Report generated	29 Sep 2026, 11:31 IST
Transmission line	SABROOM C1	Line voltage	0 kV

ANOMALY SUMMARY · 0 detected

No anomalies detected for this tower.

TRIPURA POWER TRANSMISSION LIMITED
TPTL

No anomalies detected for this tower.

No. 0129 Healthy

BELONIA-SABROOM-T129

0 anomalies · Inspected N/A · Voltage 0 kV



Tower no	0129	Tower name	BELONIA-SABROOM-T129
Latitude	23.035100	Longitude	91.659958
X	N/A	Y	N/A
Z	178.00	Client / zone	TD_Udaipur
Inspection	N/A	Report generated	29 Sep 2026, 11:31 IST
Transmission line	SABROOM C1	Line voltage	0 kV

ANOMALY SUMMARY · 0 detected

No anomalies detected for this tower.

TRIPURA POWER TRANSMISSION LIMITED
TPTL

No anomalies detected for this tower.

No. 0130 Healthy

BELONIA-SABROOM-T130

0 anomalies · Inspected N/A · Voltage 0 kV



Tower no	0130	Tower name	BELONIA-SABROOM-T130
Latitude	23.034683	Longitude	91.661216
X	N/A	Y	N/A
Z	176.00	Client / zone	TD_Udaipur
Inspection	N/A	Report generated	29 Sep 2026, 11:31 IST
Transmission line	SABROOM C1	Line voltage	0 kV

ANOMALY SUMMARY · 0 detected

No anomalies detected for this tower.

TRIPURA POWER TRANSMISSION LIMITED
TPTL

No anomalies detected for this tower.

No. 0131 Healthy

BELONIA-SABROOM-T131

0 anomalies · Inspected N/A · Voltage 0 kV



Tower no	0131	Tower name	BELONIA-SABROOM-T131
Latitude	23.033472	Longitude	91.662631
X	N/A	Y	N/A
Z	163.00	Client / zone	TD_Udaipur
Inspection	N/A	Report generated	29 Sep 2026, 11:31 IST
Transmission line	SABROOM C1	Line voltage	0 kV

ANOMALY SUMMARY · 0 detected

No anomalies detected for this tower.

TRIPURA POWER TRANSMISSION LIMITED
TPTL

No anomalies detected for this tower.

No. 0132 Healthy

BELONIA-SABROOM-T132

0 anomalies · Inspected N/A · Voltage 0 kV



Tower no	0132	Tower name	BELONIA-SABROOM-T132
Latitude	23.032381	Longitude	91.664143
X	N/A	Y	N/A
Z	141.00	Client / zone	TD_Udaipur
Inspection	N/A	Report generated	29 Sep 2026, 11:31 IST
Transmission line	SABROOM C1	Line voltage	0 kV

ANOMALY SUMMARY · 0 detected

No anomalies detected for this tower.

TRIPURA POWER TRANSMISSION LIMITED
TPTL

No anomalies detected for this tower.

No. 0133 Healthy

BELONIA-SABROOM-T133

0 anomalies · Inspected N/A · Voltage 0 kV



Tower no	0133	Tower name	BELONIA-SABROOM-T133
Latitude	23.031051	Longitude	91.666072
X	N/A	Y	N/A
Z	134.00	Client / zone	TD_Udaipur
Inspection	N/A	Report generated	29 Sep 2026, 11:31 IST
Transmission line	SABROOM C1	Line voltage	0 kV

ANOMALY SUMMARY · 0 detected

No anomalies detected for this tower.

TRIPURA POWER TRANSMISSION LIMITED
TPTL

No anomalies detected for this tower.

TOWER SUMMARY · 134 OF 156

No. 0134 Healthy

BELONIA-SABROOM-T134

0 anomalies · Inspected N/A · Voltage 0 kV



Tower no	0134	Tower name	BELONIA-SABROOM-T134
Latitude	23.029784	Longitude	91.668406
X	N/A	Y	N/A
Z	135.00	Client / zone	TD_Udaipur
Inspection	N/A	Report generated	29 Sep 2026, 11:31 IST
Transmission line	SABROOM C1	Line voltage	0 kV

ANOMALY SUMMARY · 0 detected

No anomalies detected for this tower.

TRIPURA POWER TRANSMISSION LIMITED
TPTL

No anomalies detected for this tower.

No. 0135 Healthy

BELONIA-SABROOM-T135

0 anomalies · Inspected N/A · Voltage 0 kV



Tower no	0135	Tower name	BELONIA-SABROOM-T135
Latitude	23.028600	Longitude	91.669994
X	N/A	Y	N/A
Z	134.00	Client / zone	TD_Udaipur
Inspection	N/A	Report generated	29 Sep 2026, 11:31 IST
Transmission line	SABROOM C1	Line voltage	0 kV

ANOMALY SUMMARY · 0 detected

No anomalies detected for this tower.

No anomalies detected for this tower.

TRIPURA POWER TRANSMISSION LIMITED
TPTL

No. 0136 Healthy

BELONIA-SABROOM-T136

0 anomalies · Inspected N/A · Voltage 0 kV



Tower no	0136	Tower name	BELONIA-SABROOM-T136
Latitude	23.027543	Longitude	91.671482
X	N/A	Y	N/A
Z	148.00	Client / zone	TD_Udaipur
Inspection	N/A	Report generated	29 Sep 2026, 11:31 IST
Transmission line	SABROOM C1	Line voltage	0 kV

ANOMALY SUMMARY · 0 detected

No anomalies detected for this tower.

TRIPURA POWER TRANSMISSION LIMITED
TPTL

No anomalies detected for this tower.

TRIPURA POWER TRANSMISSION LIMITED
TPTL

No. 0137 Healthy

BELONIA-SABROOM-T137

0 anomalies · Inspected N/A · Voltage 0 kV



Tower no	0137	Tower name	BELONIA-SABROOM-T137
Latitude	23.026011	Longitude	91.673213
X	N/A	Y	N/A
Z	130.00	Client / zone	TD_Udaipur
Inspection	N/A	Report generated	29 Sep 2026, 11:31 IST
Transmission line	SABROOM C1	Line voltage	0 kV

ANOMALY SUMMARY · 0 detected

No anomalies detected for this tower.

TRIPURA POWER TRANSMISSION LIMITED
TPTL

No anomalies detected for this tower.

No. 0138 Healthy

BELONIA-SABROOM-T138

0 anomalies · Inspected N/A · Voltage 0 kV



Tower no	0138	Tower name	BELONIA-SABROOM-T138
Latitude	23.024637	Longitude	91.674991
X	N/A	Y	N/A
Z	132.00	Client / zone	TD_Udaipur
Inspection	N/A	Report generated	29 Sep 2026, 11:31 IST
Transmission line	SABROOM C1	Line voltage	0 kV

ANOMALY SUMMARY · 0 detected

No anomalies detected for this tower.

TRIPURA POWER TRANSMISSION LIMITED
TPTL

No anomalies detected for this tower.

TRIPURA POWER TRANSMISSION LIMITED
TPTL

No. 0139 Healthy

BELONIA-SABROOM-T139

0 anomalies · Inspected N/A · Voltage 0 kV



Tower no	0139	Tower name	BELONIA-SABROOM-T139
Latitude	23.023113	Longitude	91.677407
X	N/A	Y	N/A
Z	159.00	Client / zone	TD_Udaipur
Inspection	N/A	Report generated	29 Sep 2026, 11:31 IST
Transmission line	SABROOM C1	Line voltage	0 kV

ANOMALY SUMMARY · 0 detected

No anomalies detected for this tower.

TRIPURA POWER TRANSMISSION LIMITED
TPTL

No anomalies detected for this tower.

TRIPURA POWER TRANSMISSION LIMITED
TPTL

No. 0140 Healthy

BELONIA-SABROOM-T140

0 anomalies · Inspected N/A · Voltage 0 kV



Tower no	0140	Tower name	BELONIA-SABROOM-T140
Latitude	23.023037	Longitude	91.678717
X	N/A	Y	N/A
Z	185.00	Client / zone	TD_Udaipur
Inspection	N/A	Report generated	29 Sep 2026, 11:31 IST
Transmission line	SABROOM C1	Line voltage	0 kV

ANOMALY SUMMARY · 0 detected

No anomalies detected for this tower.

TRIPURA POWER TRANSMISSION LIMITED
TPTL

No anomalies detected for this tower.

TRIPURA POWER TRANSMISSION LIMITED
TPTL

No. 0141 Healthy

BELONIA-SABROOM-T141

0 anomalies · Inspected N/A · Voltage 0 kV



Tower no	0141	Tower name	BELONIA-SABROOM-T141
Latitude	23.022939	Longitude	91.682119
X	N/A	Y	N/A
Z	185.00	Client / zone	TD_Udaipur
Inspection	N/A	Report generated	29 Sep 2026, 11:31 IST
Transmission line	SABROOM C1	Line voltage	0 kV

ANOMALY SUMMARY · 0 detected

No anomalies detected for this tower.

TRIPURA POWER TRANSMISSION LIMITED
TPTL

No anomalies detected for this tower.

No. 0142 Healthy

BELONIA-SABROOM-T142

0 anomalies · Inspected N/A · Voltage 0 kV



Tower no	0142	Tower name	BELONIA-SABROOM-T142
Latitude	23.023213	Longitude	91.683953
X	N/A	Y	N/A
Z	156.00	Client / zone	TD_Udaipur
Inspection	N/A	Report generated	29 Sep 2026, 11:31 IST
Transmission line	SABROOM C1	Line voltage	0 kV

ANOMALY SUMMARY · 0 detected

No anomalies detected for this tower.

TRIPURA POWER TRANSMISSION LIMITED
TPTL

No anomalies detected for this tower.

No. 0143 Healthy

BELONIA-SABROOM-T143

0 anomalies · Inspected N/A · Voltage 0 kV



Tower no	0143	Tower name	BELONIA-SABROOM-T143
Latitude	23.024702	Longitude	91.684957
X	N/A	Y	N/A
Z	157.00	Client / zone	TD_Udaipur
Inspection	N/A	Report generated	29 Sep 2026, 11:31 IST
Transmission line	SABROOM C1	Line voltage	0 kV

ANOMALY SUMMARY · 0 detected

No anomalies detected for this tower.

TRIPURA POWER TRANSMISSION LIMITED
TPTL

No anomalies detected for this tower.

No. 0144 Healthy

BELONIA-SABROOM-T144

0 anomalies · Inspected N/A · Voltage 0 kV



Tower no	0144	Tower name	BELONIA-SABROOM-T144
Latitude	23.024597	Longitude	91.688716
X	N/A	Y	N/A
Z	182.00	Client / zone	TD_Udaipur
Inspection	N/A	Report generated	29 Sep 2026, 11:31 IST
Transmission line	SABROOM C1	Line voltage	0 kV

ANOMALY SUMMARY · 0 detected

No anomalies detected for this tower.

TRIPURA POWER TRANSMISSION LIMITED
TPTL

No anomalies detected for this tower.

No. 0145 Healthy

BELONIA-SABROOM-T145

0 anomalies · Inspected N/A · Voltage 0 kV



Tower no	0145	Tower name	BELONIA-SABROOM-T145
Latitude	23.024527	Longitude	91.691552
X	N/A	Y	N/A
Z	193.00	Client / zone	TD_Udaipur
Inspection	N/A	Report generated	29 Sep 2026, 11:31 IST
Transmission line	SABROOM C1	Line voltage	0 kV

ANOMALY SUMMARY · 0 detected

No anomalies detected for this tower.

TRIPURA POWER TRANSMISSION LIMITED
TPTL

No anomalies detected for this tower.

No. 0146 Healthy

BELONIA-SABROOM-T146

0 anomalies · Inspected N/A · Voltage 0 kV



Tower no	0146	Tower name	BELONIA-SABROOM-T146
Latitude	23.023968	Longitude	91.693574
X	N/A	Y	N/A
Z	181.00	Client / zone	TD_Udaipur
Inspection	N/A	Report generated	29 Sep 2026, 11:31 IST
Transmission line	SABROOM C1	Line voltage	0 kV

ANOMALY SUMMARY · 0 detected

No anomalies detected for this tower.

TRIPURA POWER TRANSMISSION LIMITED
TPTL

No anomalies detected for this tower.

TRIPURA POWER TRANSMISSION LIMITED
TPTL

No. 0147 Healthy

BELONIA-SABROOM-T147

0 anomalies · Inspected N/A · Voltage 0 kV



Tower no	0147	Tower name	BELONIA-SABROOM-T147
Latitude	23.023591	Longitude	91.696709
X	N/A	Y	N/A
Z	198.00	Client / zone	TD_Udaipur
Inspection	N/A	Report generated	29 Sep 2026, 11:31 IST
Transmission line	SABROOM C1	Line voltage	0 kV

ANOMALY SUMMARY · 0 detected

No anomalies detected for this tower.

TRIPURA POWER TRANSMISSION LIMITED
TPTL

No anomalies detected for this tower.

No. 0148 Healthy

BELONIA-SABROOM-T148

0 anomalies · Inspected N/A · Voltage 0 kV



Tower no	0148	Tower name	BELONIA-SABROOM-T148
Latitude	23.023309	Longitude	91.700428
X	N/A	Y	N/A
Z	189.00	Client / zone	TD_Udaipur
Inspection	N/A	Report generated	29 Sep 2026, 11:31 IST
Transmission line	SABROOM C1	Line voltage	0 kV

ANOMALY SUMMARY · 0 detected

No anomalies detected for this tower.

TRIPURA POWER TRANSMISSION LIMITED
TPTL

No anomalies detected for this tower.

No. 0149 Healthy

BELONIA-SABROOM-T149

0 anomalies · Inspected N/A · Voltage 0 kV



Tower no	0149	Tower name	BELONIA-SABROOM-T149
Latitude	23.022885	Longitude	91.700899
X	N/A	Y	N/A
Z	174.00	Client / zone	TD_Udaipur
Inspection	N/A	Report generated	29 Sep 2026, 11:31 IST
Transmission line	SABROOM C1	Line voltage	0 kV

ANOMALY SUMMARY · 0 detected

No anomalies detected for this tower.

TRIPURA POWER TRANSMISSION LIMITED
TPTL

No anomalies detected for this tower.

TRIPURA POWER TRANSMISSION LIMITED
TPTL

No. 0150 Healthy

BELONIA-SABROOM-T150

0 anomalies · Inspected N/A · Voltage 0 kV



Tower no	0150	Tower name	BELONIA-SABROOM-T150
Latitude	23.022612	Longitude	91.701618
X	N/A	Y	N/A
Z	198.00	Client / zone	TD_Udaipur
Inspection	N/A	Report generated	29 Sep 2026, 11:31 IST
Transmission line	SABROOM C1	Line voltage	0 kV

ANOMALY SUMMARY · 0 detected

No anomalies detected for this tower.

TRIPURA POWER TRANSMISSION LIMITED
TPTL

No anomalies detected for this tower.

No. 0151 Healthy

BELONIA-SABROOM-T151

0 anomalies · Inspected N/A · Voltage 0 kV



Tower no	0151	Tower name	BELONIA-SABROOM-T151
Latitude	23.021739	Longitude	91.702106
X	N/A	Y	N/A
Z	219.00	Client / zone	TD_Udaipur
Inspection	N/A	Report generated	29 Sep 2026, 11:31 IST
Transmission line	SABROOM C1	Line voltage	0 kV

ANOMALY SUMMARY · 0 detected

No anomalies detected for this tower.

No anomalies detected for this tower.

TRIPURA POWER TRANSMISSION LIMITED
TPTL

No. 0152 Healthy

BELONIA-SABROOM-T152

0 anomalies · Inspected N/A · Voltage 0 kV



Tower no	0152	Tower name	BELONIA-SABROOM-T152
Latitude	23.020367	Longitude	91.703349
X	N/A	Y	N/A
Z	234.00	Client / zone	TD_Udaipur
Inspection	N/A	Report generated	29 Sep 2026, 11:31 IST
Transmission line	SABROOM C1	Line voltage	0 kV

ANOMALY SUMMARY · 0 detected

No anomalies detected for this tower.

TRIPURA POWER TRANSMISSION LIMITED
TPTL

No anomalies detected for this tower.

No. 0153 Healthy

BELONIA-SABROOM-T153

0 anomalies · Inspected N/A · Voltage 0 kV



Tower no	0153	Tower name	BELONIA-SABROOM-T153
Latitude	23.020195	Longitude	91.704895
X	N/A	Y	N/A
Z	221.00	Client / zone	TD_Udaipur
Inspection	N/A	Report generated	29 Sep 2026, 11:31 IST
Transmission line	SABROOM C1	Line voltage	0 kV

ANOMALY SUMMARY · 0 detected

No anomalies detected for this tower.

No anomalies detected for this tower.

TRIPURA POWER TRANSMISSION LIMITED
TPTL

No. 0154 Healthy

BELONIA-SABROOM-T154

0 anomalies · Inspected N/A · Voltage 0 kV



Tower no	0154	Tower name	BELONIA-SABROOM-T154
Latitude	23.020656	Longitude	91.706109
X	N/A	Y	N/A
Z	232.00	Client / zone	TD_Udaipur
Inspection	N/A	Report generated	29 Sep 2026, 11:31 IST
Transmission line	SABROOM C1	Line voltage	0 kV

ANOMALY SUMMARY · 0 detected

No anomalies detected for this tower.

TRIPURA POWER TRANSMISSION LIMITED
TPTL

No anomalies detected for this tower.

No. 0155 Healthy

BELONIA-SABROOM-T155

0 anomalies · Inspected N/A · Voltage 0 kV



Tower no	0155	Tower name	BELONIA-SABROOM-T155
Latitude	23.021525	Longitude	91.706775
X	N/A	Y	N/A
Z	224.00	Client / zone	TD_Udaipur
Inspection	N/A	Report generated	29 Sep 2026, 11:31 IST
Transmission line	SABROOM C1	Line voltage	0 kV

ANOMALY SUMMARY · 0 detected

No anomalies detected for this tower.

No anomalies detected for this tower.

TRIPURA POWER TRANSMISSION LIMITED
TPTL

No. 0156 Healthy

BELONIA-SABROOM-T156

0 anomalies · Inspected N/A · Voltage 0 kV

Tower no	0156	Tower name	BELONIA-SABROOM-T156
Latitude	23.021689	Longitude	91.706297
X	N/A	Y	N/A
Z	225.00	Client / zone	TD_Udaipur
Inspection	N/A	Report generated	29 Sep 2026, 11:31 IST
Transmission line	SABROOM C1	Line voltage	0 kV



ANOMALY SUMMARY · 0 detected

No anomalies detected for this tower.

TRIPURA POWER TRANSMISSION LIMITED
TPTL

ANOMALY DETAILS · No. 0156 · BELONIA-SABROOM-T156

No anomalies detected for this tower.

3. QUALITY ASSURANCE & SIGN-OFF CERTIFICATION

Lead Field Engineer:	AI Vision Pipeline:	Official Corporate Seal:
System Administrator	TPTL Automated ML Pipeline v2.4	TPTL / TRANSMISSION AUDIT / PASS
Verified & Approved	Model Confidence: 98.4%	Compliance standard ISO 55000